



Service Request Summary

SERVICE REQUEST #:	513530	SERVICE DESCRIPTION:	Other Road or Sidewalk Compliant
--------------------	--------	----------------------	----------------------------------

Date:	9/24/2026 10:00:58 AM	Subdivision:	6
Initiated By:	Citysourced, Admin	Schedule:	610 UTIL
Dispatched To:	Cardarelli, Dan	District:	
Status:	COMPLETE	Supervisor:	Dorsey, Nyrah

Locate Information

Ticket No.:

Address:	537 WYNGATE RD
Location:	537 WYNGATE RD, LUTHERVILLE, MD, 21093

Details:	Description: There is a hole in the cover in the road- a tripping hazard and a possible hazard for dogs Image: http://s3.citysourced.com.s3.amazonaws.com/FileStorage/2026-09/b9c3ee89002545499f057e42daadc5ff.jpg
----------	---

CALLER INFORMATION

First Name:	MITCHELL	Email:	JMITCHC@ICLOUD.COM
Last Name:	CROOK	Phone:	
Call Time:	9/24/2026 10:01:24 AM	Cell Phone:	4103715687
Caller Type:			

ADDITIONAL INFORMATION

Comments

Related Work Order No(s):

No related work orders



Service Request Summary

SERVICE REQUEST #: 513530

SERVICE DESCRIPTION: Other Road or Sidewalk Compliant

9/24/2026 10:01:48 AM

Description: There is a hole in the cover in the road- a tripping hazard and a possible hazard for dogs

OneView Id: 312786

Device Type: Apple

Device Model: iPhone14,2

Approximate Address: 537 WYNGATE RD, LUTHERVILLE, MD, 21093

Lat/Lng Coordinates: 39.4495206, -76.588325

OriginationIpAddress: 104.23.190.254

AttachedMediaCount: 1

OneViewIsRequestTypeIntegrated: True

OneViewDynamicsCreateJobCompleted: True

OneViewIntegrationId: 2

OneViewPostReport: SOAP Url=https://baltimorecountymd-oneview.rocksolid.com/XRMServices/2011/Organization.svc

OneViewTicketDisplay: CAS-4992767-S2J8V1

OneViewTicketId: a7855f64-20b8-f111-a8a7-000d3a0f8a39

Image: <http://s3.citysourced.com.s3.amazonaws.com/FileStorage/2026-09/b9c3ee89002545499f057e42daadc5ff.jpg>

9/24/2026 3:39:23 PM

Nyhra can you send this to City Water Please.