

Inspections: Damaged Pole Report

Service Request: 2600909140 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 1620 W. Baltimore St
Grid : 3010240 LLC: 7493

Descriptive Location and Comments:

Street: W. Baltimore St
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O ☒ S/O _____ W/O _____
Street or Landmark: N. Vincent St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein ☒

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes ☒
No _____

Bolts
Wires
Conduit

☒
☒
☒

Metal
Concrete ☒

Date: 9/24/2026 Inspector's Signature: J. Crowder - 8512



There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

30102407493

REPORT THIS LIGHT

Service Request Summary Report**26-00909140**

Printed Date: Sep 25, 2026 - 8:29:22 AM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00909140
Priority: Standard
Status: Pending
Status Date: Sep 25, 2026 8:27:39 AM
Created Date: Sep 25, 2026 8:27:19 AM
Overdue on: Nov 27, 2026 7:27:19 AM
Closed on:

Location: 1620 W BALTIMORE ST, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		9/25/2026 8:27 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010210
Assign inspector	LLC / POLE #	7493
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Otterbein
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Missing pole report created G Crowder9-24-26	Gregory Crowder	9/25/2026 8:29 AM	Private
Assign inspector : Missing pole report created G	Gregory Crowder	9/25/2026 8:29 AM	Public