

Inspections: Damaged Pole Report

Service Request: 26-00905829 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 759 YALE Ave
 Grid : 3020430 LLC: 7054

Descriptive Location and Comments:

Street: Yale Ave
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: S. Woodington Rd

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 9/28/2026 Inspector's Signature: J. Crowder - 8512



12th LED PMA

Service Request Summary Report
26-00905829
Printed Date: Sep 28, 2026 - 1:48:02 PM

Type: BGE-StLight Pole Installation
Created By: Erica Roundtree
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00905829
Priority: Urgent
Status: Pending
Status Date: Sep 28, 2026 1:42:11 PM
Created Date: Sep 24, 2026 11:13:00 AM
Overdue on: Nov 27, 2026 3:09:24 PM
Closed on:

Location: 759 YALE AVE, Baltimore City, 21229
Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
byron lewis			+1 (443) 991-2159

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		9/28/2026 1:42 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020430
Assign inspector	LLC / POLE #	7054
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Missing pole report created G Crowder	Gregory Crowder	9/28/2026 1:43 PM	Private
9-28-26			
Assign inspector : Missing pole report created G Crowder	Gregory Crowder	9/28/2026 1:43 PM	Public