

Inspections: Damaged Pole Report

Service Request: 26-00963220 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3831 Oakford Ave

Grid : 1030410 LLC: 7045

Descriptive Location and Comments:

Street: OAKford Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th ☒ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Ayndale Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Bolts
Wires
Conduit

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 10/15/2026 Inspector's Signature: J. Crowder - 8512



DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-645-0173** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

10304107045

REPORT THIS LIGHT

Service Request Summary Report**26-00963220**

Printed Date: Oct 19, 2026 - 8:28:22 AM

Type: BGE-StLight Pole Installation
Created By: Shanell Gorie
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00963220
Priority: Urgent
Status: Pending
Status Date: Oct 19, 2026 8:28:15 AM
Created Date: Oct 13, 2026 11:50:52 AM
Overdue on: Dec 16, 2026 2:52:37 PM
Closed on:

Location: 3831 OAKFORD AVE, Baltimore City,
21215

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		10/15/2026 8:26 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030410
Assign inspector	LLC / POLE #	7045
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Missing pole report created G Crowder-10-15-26	Gregory Crowder	10/19/2026 8:28 AM	Private
Assign inspector : Missing pole report created G Crowder	Gregory Crowder	10/19/2026 8:28 AM	Public