11/17/26 Waiting on Frank to Send over

Inspections: Damaged Pole Report

Service Request: _____ Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3302 Piedmont Ave

Grid : 1020440 LLC: 7237

Descriptive Location and Comments:

Street: N. Hilton St

Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ✓ E/O _____ S/O _____ W/O _____

Street or Landmark: Piedmont Ave

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Need new base

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
200 ✓
250 _____
400 _____
1000 _____

Arm:

6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ✓

Base Condition: **Good** **Bad:**

Bolts ✓ _____
Wires ✓ _____
Conduit ✓ _____

Base Type:

Metal ✓
Concrete _____

Date: 11/17/2026 Inspector's Signature J. Crowder - 8512



25ft Cobra Head LED

Service Request Summary Report
26-01063355
Printed Date: Nov 19, 2026 - 8:30:37 AM

Type:	BGE-StLight Pole Installation	**SR #:**	26-01063355
Created By:	Richard Stewart	**Prority:**	Urgent
Service Request Owner:	BGE	**Status:**	Open
Method Received:	Phone	**Status Date:**	Nov 19, 2026 8:30:33 AM
SLA Detail:	45 Business Days	**Created Date:**	Nov 17, 2026 12:37:57 PM
		Overdue on:	Jan 20, 2027 4:53:48 PM
		Closed on:	
Location:	3300 PIEDMONT AVE, Baltimore City, 21216		
Location Details:			
Description:			

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		11/19/2026 8:27 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020440
Assign inspector	LLC / POLE #	7237
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Service Response : New Comment was added in Destination System: bge pole installation	citizen Site Guest User	11/18/2026 4:45 PM	Private
Service Response : New Comment was added in	citizen Site Guest User	11/18/2026 4:45 PM	Private