

Inspection Report

Hugo Brennenstuhl GmbH & Co. KG, China Representative Office

Room 2306B Waitan Mansion, No.132 Renmin Road, Ningbo.

Tel:0086-574-87655585 Fax:0086-574-87655669

www.brennenstuhl.com E-mail:wilson@cn.brennenstuhl.com

Report No. 520026_1290050_1

Date	2023-02-20	Supplier Name	Siterwell(De)			Supplier No. Production week	4211/0523
Order No.	520026	Art.No.	1290050			Inspection Instruction No.	297
Total Qty.	12960 pcs	Tested Quantity	Special inspection Level:S-2	8 pcs		Inspector	Howar Shao
			General inspection Level:I	125 pcs			
No.	Problem description		Class of failure			Result	
			A	B	C		
1	No						
SUM							
Rework details of the problems	No						
Improved points out of last reports	No						
Decision	Release						
Quality evaluation	☆☆☆		Service evaluation		☆☆☆		
Remarks	PLEASE NOTE THAT THIS INSPECTION RESULT IS GIVEN UNDER THE CONDITION THAT THERE ARE NO ADDITIONAL FINDINGS DURING INCOMING INSPECTION AT THE HUGO BRENNENSTUHL GROUP.						

Product Information and main checker (if checked, mark ✓, if not, keep it blank)
产品信息及主要检查员(如检查员已检查, 请打钩, 否则保持空白)

序号	检查项目	检查员	检查日期	检查结果	备注
1	外观检查	✓	✓	✓	
2	功能检查	✓	✓	✓	
3	安全性能	✓	✓	✓	
4	性能测试	✓	✓	✓	
5	包装检查	✓	✓	✓	
6	文件检查	✓	✓	✓	
7	其他	✓	✓	✓	

Product main tests (if the test is done or open, please mark ✓, if not, please keep it blank)
产品主要测试项目(如检查员已检查, 请打钩, 否则保持空白)

序号	测试项目	测试员	测试日期	测试结果	备注
1	外观测试	✓	✓	✓	
2	功能测试	✓	✓	✓	
3	安全性能	✓	✓	✓	
4	性能测试	✓	✓	✓	
5	包装测试	✓	✓	✓	
6	文件测试	✓	✓	✓	
7	其他	✓	✓	✓	

重要提示: 检查员必须在产品出厂前, 对产品进行严格检查, 确保产品质量。如有不合格产品, 请及时反馈给相关部门。
重要提示: 检查员必须在产品出厂前, 对产品进行严格检查, 确保产品质量。如有不合格产品, 请及时反馈给相关部门。

215_7239. JPG



1290050 (1). JPG



1290050 (2). JPG