

Location: SunState Equipment
San Jose CA

TRUCK AND EQUIPMENT CONSULTING LLC - DUMP TRUCK

Date 8/11/2022
 (Y/M/D)
 Inspector Initials H.H.

(Basic Information)	
(Make)	Ford
(Model)	F550 S Duty XL Reg Cab 4x2 Dualie Rear
(Serial Number)	1FDUF5GT7DEB53590
(Year of Manufacturing/Origin)	2013 (built 5/2013)
(Color)	White / Gray
(Mileage)	87,513.6 Miles
(Engine)	PowerStroke 6.7L 390Hp V8 Turbo Diesel
(Transmission)	Automatic 6 Spd
(Dump Capacity)	3 yd3

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions	
GVWR	19,500 lbs
Body	Valew Dump Body
DOT	CALIF Perm Fleet - Sept
Brake	Hydraulic
Front / Rear Axle	Front =6500 lbs / Rear =14,706 lbs
Tires	Continental 225/70R 19.5
PTO	Floor Mount
Rear	4.88
Wheelbase	141 inch
Origin	Louisville, Kentucky USA
Other	Pulltarps Tarp System, Fed Annual Insp 2/2022

	(Check List)	A	B	C	D	E	(Remarks)
	(General Appearance-Rear)	X	X				Good appearance rear dump body Minor surface paint cosmetics+2 dents
	(General Appearance-Right)	X					Right side panels+gaps Good appearance No damage Side wood slats worn
	(General Appearance-Left)	X					Left side panels+gaps Good appearance No damage Dump panels straight
	(General Appearance-Upper)	X					Good appearance upper body+panel gaps, roof,hood Dump No damage
	(Major / Minor Surface Rust)	X					No rust issues or rust damage Surface paint cosmetics on dump body
	(Body Panels / Covers - Rust Damage / Cancer)	X					No rust cancer Minor rear surface scrapes+paint cosmetics No damage
	(Visible Weld Repairs / Stress Cracks)	X					None seen
	(Glass Condition)	X					Good Glass
	(Chassis / Undercarriage Damage)	X					Good appearance Frame rails, underside components Dry appearance
	(Operator Cabin)	X					Dirty Solid floors dash+steering wheel Good appearance No damage
OPERATOR'S COCKPIT	(Operator Controls and Switches)	X					Complete No broken switches or controls
	(Odometer Activity)	X					Working
	(Other Gauge Activity)	X					Gauges+display Working No Check Engine or Service Indicators lit
	(Door / Canopy Latches)	X					Good Hood + Door latch function
	(Safety - Horn / First Aid Kit)	X					Horn Working
	(Operator Seat Condition)	X					Seats Good condition
	(Other)	X					A/C working
E N G I N E	(Oil Color / Fluid Appearance)	X					Normal Appearance No Blow-By at operating temp
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)	X					Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color - White / Blue / Black / Clear)	X					Clear / Clear at Temperature
	(Oil Leaks)	X					No dampness or wet areas Dry appearance
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)	X					No smoke issues
	(Coolant Color / Fluid Appearance)	X					Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)	X					No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)	X					None seen Some dented radiator fins
	(Overall Engine Appearance Clean / Wet / Dry)	X					Good Dry appearance No rust. No dried seepages seen

ELECTRICAL	(Lighting System Condition)	X				Working
	(Reverse Alarm / Backup Signal)	X				Working
	(Battery Condition)	X				Good appearance battery + battery terminals
	(Other Electric Device Condition)	X				Good PTO + Dump control function
TIRES	FRONT TRACTOR TIRES	X				Tires =B Good appearance No side wall damage Inner Hubs Dry =B no rust
	TRAILER TIRES X4	X	X			Tires =B Good appearance R.Rear tire =C/C+ Inner Hubs =B dry no rust
	OTHER	X				Tires + Hubs overall Good appearance
TRANSMISSION	(Clutch Noise / Function)	X				No unusual transmission noises or vibrations
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	(Other Remarks)	X				Pedals Good appearance No damage from wear or tear
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard Dry appearance
B R A K E S	(Foot Brake)	X				Good Brake Function
	(AIR BRAKE)					N/A
	(Parking Brake)	X				Good function
DUMP and HYDRAULICS	LIFT + DUMP	X				Good Lift + Drop function
	HYDRAULICS	X				Working
OPERATION	TARP	X				Tarp + frame system Good appearance and function
	PUMP PERFORMANCE	X				Good function No unusual noises
	FORWARD & REVERSE	X				Good Forward and Reverse function
	STEERING + BRAKES	X				Good Steering and Brakes function
	ENGINE	X				Engine Smooth Idle Good Response
	CONTROLS	X				Driver Controls + Switches Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X				Good body panels,panel gaps, Hydraulics clean+dry No pitting or seepages
	COMMENTS	X				Minimal cosmetics only minor surface scratches + 2 dents rear panel
	OVERALL PERFORMANCE INSPECTION	X				Good travel performance Good steering+brakes Good engine response
	COMMENTS	X				Good dump lift and drop function + performance

TIRES

OVERALL EXTERIOR RATING: B QUALITY: B

OVERALL INTERIOR RATING: B SAFETY: B

OVERALL PERFORMANCE: B FUNCTIONALITY: B

OVERALL CONDITION GRADE: B

FLUID SAMPLE REQUEST (Y/N) n OIL n COOLANT n

*A:Remaining Ratio 90% or more
 *B:Remaining Ratio 70% or more
 *C:Remaining Ratio 50% or more
 *D:Remaining Ratio 20% or more
 *E:Remaining Ratio 20% or less