

Location: Rivera Hauling
Sylmar CA

TRUCK AND EQUIPMENT CONSULTING LLC – TRACK LOADER SKID STEER CHECKLIST
(REQUIRED)

Date 12/13/2022
 Inspector Initials L.W.

(Basic Information)	
(Manufacturer)	Kubota
(Model Number)	SSVL75-2 WC (wide track +cab)
(Serial Number) (S/N Label faded)	KBCC0752TK1F44794
(Year of Manufacturing)	2019
(Hour Meter Reading)	408.1 Hrs
(Transmission/Drive)	Hi – Low 2 Spd
(Engine Model)	TIER 4 Kubota V3307CR-TE4 3.3L 68Hp 14 Turbo
(Hydraulic System/Hydraulic Tank)	Hyd Sys =15.9 gal / Hyd Tank =9.2 gal
(Hydraulic Relief)	Std Flow Hydraulics 3185 psi / 17.4 gpm

Specification and Dimensions	
Serial Plate/Frame Inscription	KBCC0752TK1F44794
Cabin+Canopy (Circle)	Open Cab w/Rear Glass + Side Grilles
EPA Certificate / Permits Posted	ROPS / FOPS
Attachment	Bucket with Deflectors
Tracks	Wide Option Track =15 in / Length =56.5 in
Operating Weight	9039 lbs
Load Capacity	Op Capacity =2300 lbs / Tipping Load =6570 lbs
Track Rollers	Track Rollers =4 (per side)
Track Gauge/Ground Pressure	Gauge =53.3 in/ 4.7 psi
Other	Aux Hydraulics, Radio, Rear View Mirror 24.6 gal Fuel capacity

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

	(Check List)	A	B	C	D	E	(Remarks)
GENERAL APPEARANCE	(General Appearance-Front)		X				Good appearance front components,panels+panel gaps,no wear issues
	(General Appearance-Rear)		X	X			Good appearance Some minor surface scratches+scrapes Cosmetic only
	(General Appearance-Right)		X				Good appearance right components,panels+panel gaps,no wear issues
	(General Appearance-Left)		X				Good appearance left components,panels+panel gaps,no wear issues
	(General Appearance-Upper)		X				Upper cab surfaces,roof panels+engine covers+panels Good appearance
	(Major / Minor Surface Rust)		X				No rust issues No rust cosmetics
	(Body Panel Rust Damage / Cancer)		X				No panel damages No dents No dings No rust
	(Visible Weld Repairs / Stress Cracks)		X				No patches or panels damages seen
	(Glass / Polycarbonate ? Condition ?)		X				Rear Glass Good appearance No damage
	(Chassis / Undercarriage Damage)		X				Good appearance underside panels Dry appearance
OPERATOR'S COCKPIT	(Operator Cabin)		X				Clean and straight Solid floors,Good panels, Good joysticks
	(Operator Controls and Switches)		X				Good appearance Operator controls Complete and working
	(Hour Meter Activity)		X				Working
	(Other Gauge Activity)		X				Working
	(Door / Canopy Latches)		X				Engine cover panel+latches Good working condition
	(Safety – Horn / First Aid Kit)		X				Working
	(Operator Seat Condition)		X				Seat Good Condition
	(Safety – Seat Belts / Fire Extinguisher)		X				Yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		X				Clean + Dry Good appearance No blow by seen at operating temps
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start Smooth Idle No unusual noise at startup or shut down
	(Engine Exhaust Color – White / Blue / Black / Clear)		X				Clear Clear at operating temp
	(Oil Leaks)		X				No active oil leaks seen from engine
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues at start up or when hot
	(Coolant Color / Fluid Appearance)		X				Good appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No noises from cooling system
	(Coolant Leaks from Radiator)		X				No radiator leaks seen Good appearance of fins
	(Overall Engine Appearance Clean / Wet / Dry)		X				Clean and Dry appearance
	(Other)		X				
HYDRAULICS OVERALL	(Overall appearance of Hydraulic lines/fittings – worn/cracked)		X				Good appearance No dried seepages No fraying Dry+clean fittings
	(Hydraulic Pump Sounds / Noises)		X				Smooth No unusual pump noises or vibrations
	(Wet or Damp hydraulic lines and fittings / fluid leaks)		X				No active leaks No dried seepages Pistons no discoloration no pitting
	(External Controls / Levers Condition)		X				Working
	(Hydraulics Service Records / Maintenance History)						not marked or labeled

ELECTRICAL	(Lighting System Condition)		X			Working	
	(Reverse Alarm / Backup Signal)		X			Working	
	(Battery Condition)		X			Battery compartment Good appearance battery + posts look good	
	(Other Electric Device Condition)		X			Driver display clear and sharp No diagnostic codes No service codes	
B R A K E S	(Foot Brake)		X			Good function No squeaks No unusual noises	
	(Inching Brake Functional & Working Condition)		X			Good function	
	(Parking Brake)		X			Good function	
	(Other Remarks)						
TRANSMISSION	(Clutch Noise / Function)		X			Smooth Shifting No unusual noises	
	(Transmission Noise / Function)		X			Good Forward and Reverse Function	
	(Shift Lever Condition & Function)		X			Shifter Good Appearance	
	(Other Remarks)						
HYDRAULICS CYLINDERS	(Lift)	(Oil Leak from Cylinder)	X			No active leaks seen	
		(Mounting Pin Condition)	X			Good appearance No wear issues	
	(Bucket)	(Oil Leak from Cylinder)	X			No active leaks seen	
		(Mounting Pin Condition)	X			Good appearance No wear issues	
	(Steering)	(Oil Leak from Cylinder)	X			No active leaks seen	
		(Mounting Pin Condition)	X			Good appearance No wear issues	
(Other Remarks)		X			Good appearance No wear issues		
C H A S S I S & COMPONENT	(Transom / Boom / Arm Function / Noise)		X			Quiet Lift + Drop No unusual noises Smooth function	
	(Slack in Pins / Loose Pins / Soft Bushings)		X			No vibration or noise	
	(Level stance and alignment)		X			Level Stance	
	(Right Track Rollers/Idler Appearance)		X			B = Good appearance Smooth surfaces no rust or wear+tear seen	
	(Left Track Rollers/Idler Appearance)		X			B = Good appearance Smooth surfaces no rust or wear+tear seen	
	(Track Guards R/L Appearance)		X			B = Good appearance Smooth surfaces no rust or wear+tear seen	
	TRACKS	(Right)	Right Upper Appearance	X			Tracks = B / B- Minimal wear+tear No damage seen
			Right Lower Appearance	X			Tracks = B / B- Minimal wear+tear No damage seen
		(Left)	Left Upper Appearance	X			Tracks = B / B- Minimal wear+tear No damage seen
			Left Lower Appearance	X			Tracks = B / B- Minimal wear+tear No damage seen
	(Tracks Overall Condition)		X			Quiet travel No squealing or noises	
Attachment	(Overall Appearance)		X			Deflectors Good appearance No damage some minor surface scratches	
	(Bucket Edge)		X			Good appearance of deflectors	
	(Bucket Articulation)		X			Good articulation of hydraulics	
	(Bucket Performance Vibrations ? Noises ?)		X			Bucket hydraulics Smooth and Quiet Performance	

OVERALL EXTERIOR RATING: B

QUALITY: B

TRANSPORT DIMENSIONS: (reff only)

*A:Remaining Ratio

90% or more

OVERALL INTERIOR RATING: B

SAFETY: B

Length: 140.8 inch (w/std bkt)

*B:Remaining Ratio

70% or more

OVERALL PERFORMANCE: B

FUNCTIONALITY: B

Width: 68 inch

*C:Remaining Ratio

50% or more

OVERALL EVALUATION GRADE: B

Height: 82 inch

*D:Remaining Ratio

20% or more

FLUID ANALYSIS RECOMMENDED (Y/N) n OIL n COOLANT n

Weight: 9039 lbs

*E:Remaining Ratio

20% or less