


Inspection Report (Backhoe Loader)

General Info

Year	2019
Make	New Holland
Model	B110C
Serial Number	FNHB110CNGHH02019
Hour Meter Reading	143 Hours
Previous Application (e.g., earth moving, mining, demolition, etc)	Home Property Use ONLY (Yard Projects)

Dimensions

Measurement Guide	
A. Length (ft and inches)	23'
B. Width (ft and inches)	7'6"
C. Height (ft and inches)	12'6"
Operational Weight (lbs)	18,523 Lbs.



Features and Configuration

Control Station Type	Cab
Loader Bucket	Yes
Loader Bucket Specs	88" General Purpose Bucket with top hooks
Backhoe Bucket	Yes
Backhoe Bucket Specs	24"
Additional Attachment(s)?	Yes
Auxiliary Hydraulics	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Other Configuration Details / Notes	1 Custom Set of Qty.3 - 48" fork attachment, comes with machine

Exterior 360 Walkaround

Inspection Report (Backhoe Loader)

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



General Appearance Inspection Points

General Appearance

Inspection Report (Backhoe Loader)

Close-up Exterior Photos



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)






Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



	
	
	
Body Panels	4 - Like New, Recently Replaced
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	4 - Like New, Recently Replaced
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	4 - Like New, Recently Replaced
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	4 - Like New, Recently Replaced

Inspection Report (Backhoe Loader)

Handrails Condition	Handrails are fully intact and appear structurally sound
Glass	4 - Like New, Recently Replaced
Glass Condition	Glass intact, no visible damage
Mirrors	4 - Like New, Recently Replaced
Mirror Condition	Mirrors present and intact, no visible damage
Exterior Lights	4 - Like New, Recently Replaced
Exterior Lights Condition	No visible damage, lighting system is operational

Control Station Inspection Points

Control Station

Control Station	Take close-up photos of operator control station or cab including the floors, panels, headliner, seat, controls & displays, gauges & meters, and interior lights. Note any damage or wear.
Serial Number Plate Photo	 <p>A close-up photograph of a metal serial number plate mounted on a yellow surface. The plate is divided into two sections. The left section contains the text: 'CNH Industrial Italia S.p.A. MADE IN ITALY', 'Type Model: B112C', 'Product Identification Number (PIN): FNHB112CNCGH02019'. The right section contains the 'NEW HOLLAND CONSTRUCTION' logo and 'CNH Industrial Italia S.p.A. Via Piava, 80 - 10138 Torino, Italia'.</p>
Operator Cabin Photos	 <p>A photograph showing the interior of the operator's cabin. The view is from the operator's perspective, looking forward. It shows the steering wheel, the control levers (joysticks), and the seat. The cabin is well-lit, and the controls appear to be in good condition.</p>


Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)





Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)

	
	
Operator Cabin Overall	4 - Like New, Recently Replaced
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Seat	4 - Like New, Recently Replaced
Operator Seat Condition	Seat(s) in good condition, no stains or tears in upholstery
Cabin Lights	4 - Like New, Recently Replaced
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Safety Lock Out / Stop	4 - Like New, Recently Replaced
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	4 - Like New, Recently Replaced
Controls & Switches Condition	All switches are installed and functional
Hour Meter Activity	4 - Like New, Recently Replaced
Hour Meter Condition	Hour meter is functional and in good condition
Other Gauge Activity	4 - Like New, Recently Replaced
Other Gauge Condition	All cockpit gauges are functional and in good condition
Heater & A/C	4 - Like New, Recently Replaced
Heater & A/C Condition	Heater and A/C work as expected



Inspection Report (Backhoe Loader)

Travel Alarm	4 - Like New, Recently Replaced
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	4 - Like New, Recently Replaced
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0

Engine Inspection Points

Engine


Engine Type (Make, Model, Cylinders, Hp)	NewHolland - 4Cyl. - 110HP - 3.4L
Emissions Tier	Tier 4F
Engine Serial Number	000324963
Engine Fuel Type	Diesel

Engine Photos	
	


Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



Inspection Report (Backhoe Loader)



	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Radiator	4 - Like New, Recently Replaced
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Belts	4 - Like New, Recently Replaced
Belt Condition	Belts appear in good condition & alignment with proper tension
Hoses	4 - Like New, Recently Replaced
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Water Pump	4 - Like New, Recently Replaced
Water Pump Condition	No unusual pump noises heard

Inspection Report (Backhoe Loader)




Cooling System Leaks	No
Coolant Color / Appearance	4 - Like New, Recently Replaced
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine in excellent condition and still looks and runs like new.

Drivetrain Inspection Points

Drivetrain

Drivetrain	Take close-up photos of the drivetrain components including transmission housing, drive shaft, drive motors, fittings, and hoses. Note any damage or wear.
Drivetrain Photos	
	

Inspection Report (Backhoe Loader)


		
		
		
Hydrostatic Transmission?	No	
Transmission Info (Make/Model/Speeds)	Powershift 4 Speed	
Transmission	4 - Like New, Recently Replaced	
Transmission Condition	No unusual noises or vibrations	

Inspection Report (Backhoe Loader)

Transmission Photos



Inspection Report (Backhoe Loader)

	
Clutch	0
Shift Lever	4 - Like New, Recently Replaced
Shift Lever Condition	Good forward and reverse function
Foot Brake	4 - Like New, Recently Replaced
Foot Brake Condition	Good brake function
Inching Brake	0
Parking Brake	4 - Like New, Recently Replaced
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in solid condition and like new.




Chassis Inspection Points

Frame	4 - Like New, Recently Replaced
Frame Photos	




Inspection Report (Backhoe Loader)






Inspection Report (Backhoe Loader)

	
	
	
Stance	4 - Like New, Recently Replaced
Front Axle Appearance	4 - Like New, Recently Replaced

Inspection Report (Backhoe Loader)

<p>Front Axle Appearance Photos</p>		
		
		
<p>Rear Axle Appearance</p>	<p>4 - Like New, Recently Replaced</p>	



Inspection Report (Backhoe Loader)

Rear Axle Appearance Photos	
	
Oscillating Pin Appearance	4 - Like New, Recently Replaced
Wheels & Tires	4 - Like New, Recently Replaced
Wheels & Tires Photos	

Inspection Report (Backhoe Loader)






Inspection Report (Backhoe Loader)

		
Tire Brand	Galaxy	
Tire Size	19.5-24 - Rear. 14-17.5 Front	
Front Left Tire - Ratio Remaining	90%	
Rear Left Tire - Ratio Remaining	90%	
Front Right Tire - Ratio Remaining	90%	
Rear Right Tire - Ratio Remaining	90%	
Lift Arm	4 - Like New, Recently Replaced	
Lift Arm Photos		




Inspection Report (Backhoe Loader)






Inspection Report (Backhoe Loader)

		
		
Chassis to Arm Pins	4 - Like New, Recently Replaced	
Tilt Linkage	4 - Like New, Recently Replaced	
Tilt Linkage Pins & Bushings	4 - Like New, Recently Replaced	
Bucket to Arm Pins	4 - Like New, Recently Replaced	
Boom Condition	4 - Like New, Recently Replaced	
Boom Condition Photos		

Inspection Report (Backhoe Loader)

	
	
<p>Stick Condition</p>	<p>4 - Like New, Recently Replaced</p>
<p>Stick Condition Photos</p>	

Inspection Report (Backhoe Loader)

	
	
Stick Extension Wear Guides	4 - Like New, Recently Replaced
Boom Lock	4 - Like New, Recently Replaced
Swing Tower Pivot	4 - Like New, Recently Replaced
Boom Base Pin & Bushings	4 - Like New, Recently Replaced
Boom to Stick Pin & Bushings	4 - Like New, Recently Replaced
Stick to Bucket Pin & Bushings	4 - Like New, Recently Replaced
Outriggers	4 - Like New, Recently Replaced
Outriggers Photos	

Inspection Report (Backhoe Loader)





Inspection Report (Backhoe Loader)




		
Overall Chassis	4 - Like New, Recently Replaced	
Overall Chassis Comments	Chassis in great condition with no problems observed during the inspection.	

Hydraulics Overall Inspection Points

Hydraulics Overall




Hydraulic System	Take close-up photos of the hydraulic components including the pump, lines, fittings, controls, and levers. Note any damage, wear, or leaks.	
Hydraulic System Photos		
		

Inspection Report (Backhoe Loader)




		
		
		
Wet or Damp Hydraulic Lines / Fittings	No	
Appearance of Hydraulic Lines / Fittings	4 - Like New, Recently Replaced	
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition	
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	

Hydraulics Cylinders Inspection Points




Inspection Report (Backhoe Loader)

Loader Lift / Tilt Cylinders	Check the lift and tilt cylinders. Note any wear, pitting, discoloration, etc. Take photos.
Loader Lift / Tilt Cylinders: Mounting Pin	4
Loader Lift / Tilt Cylinders: Oil Leaks	No
Loader Lift / Tilt Cylinders Photos	
	
	




Inspection Report (Backhoe Loader)

	
	
	
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinder: Mounting Pin	4
Steering Cylinder: Oil Leaks	No




Inspection Report (Backhoe Loader)

Steering Cylinder Photos		
		
Outrigger Cylinders	Check the outrigger cylinders. Note any wear, pitting, discoloration, etc. Take photos.	
Boom Swing / Lift Cylinders	Check the boom swing and lift cylinders. Note any wear, pitting, discoloration, etc. Take photos.	
Boom Swing / Lift Cylinders: Mounting Pin	4	
Boom Swing / Lift Cylinders: Oil Leaks	No	
Boom Swing / Lift Cylinders Photos		

Inspection Report (Backhoe Loader)

	
	
Stick Cylinder	Check the stick cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Stick Cylinder: Mounting Pin	4
Stick Cylinder: Oil Leaks	No
Stick Cylinder Photos	




Inspection Report (Backhoe Loader)

		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder: Mounting Pin	4	
Bucket Cylinder: Oil Leaks	No	
Bucket Cylinder Photos		
		




Bucket Inspection Points

Loader Bucket	4 - Like New, Recently Replaced
----------------------	---------------------------------



Inspection Report (Backhoe Loader)

<p>Loader Bucket Photos</p>		
		
		

Inspection Report (Backhoe Loader)

	
Loader Bucket Edge / Deflectors	4 - Like New, Recently Replaced
Backhoe Bucket	4 - Like New, Recently Replaced
Backhoe Bucket Photos	
	

Inspection Report (Backhoe Loader)

	
	
Backhoe Bucket Edge / Deflectors	4 - Like New, Recently Replaced

Additional Attachments

Additional Attachment(s)

Additional Attachments

Attachment Type	Custom Fork Tool (Quick Connect to Existing Top of Loader Bucket Hooks)
Attachment Make	Custom
Attachment Size / Specs	3 Forks 48" (Adjustable via slide on bar)
Attachment Condition	4 - Like New, Recently Replaced
Comments	Easily connected to top front Loader Bucket Top Hooks

Inspection Report (Backhoe Loader)

Attachment Photos



Inspection Report (Backhoe Loader)



Functional Test

Forward & Reverse	4 - Like New, Recently Replaced
Steering	4 - Like New, Recently Replaced
Loader Bucket Functionality	4 - Like New, Recently Replaced
Backhoe Bucket Functionality	4 - Like New, Recently Replaced
Overall Functional Test Comments	All functions operate like new. Machine in low use excellent working condition.
Operating Video	Click to Download
Additional Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	4 - Like New, Recently Replaced
Interior Rating	4 - Like New, Recently Replaced
Safety Rating	4 - Like New, Recently Replaced
Quality Rating	4 - Like New, Recently Replaced
Functionality Rating	4 - Operating Within Factory Spec
Overall Rating	4 - Like New, Recently Replaced
What's Great About the Machine	This Machine has less than 200 hours and most of it has been light duty type of work. The owner/operator mainly used the machine for property projects and the machine is still like new.
What Needs Work	N/A
Date/Time	02-21-2023