

9/26/22 9:44:04

Equipment Maintenance History

Cmpy: SS

System: SUNSTATE

Page: 17

Equipment: 166355

Cat/Class: 55-5780

SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
19890662	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	16414	16.700	3/18/22	34		100	16.700	AU2
19890662	LOCK OUT TAG DOWN EQUIP	16414	16.700	3/18/22	164		100	16.700	AU2
19890662	EQUIP LOCK OUT HAS BEEN REMOVED	16414	16.700	3/18/22	165		100	16.700	AU2
19890662	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	16414	16.700	3/18/22	193		100	16.700	AU2
19890662	CHECK CONDITION OF PAINT AND DECALS	16414	16.700	3/18/22	435		100	16.700	AU2
19890662	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16414	16.700	3/18/22	530		100	16.700	AU2
19890662	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16414	16.700	3/18/22	563		100	16.700	AU2
19890662	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16414	16.700	3/18/22	636		100	16.700	AU2
19890662	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16414	16.700	3/18/22	637		100	16.700	AU2
19890662	GEN 6 PCON DECAL REPLACEMENT CHECKED	16414	16.700	3/18/22	647		100	16.700	AU2
19890662	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16414	16.700	3/18/22	653		100	16.700	AU2
19626414	LOCK OUT TAG DOWN EQUIP	17399	1.610	12/08/21	164		100	1.610	AUS
19626414	EQUIP LOCK OUT HAS BEEN REMOVED	17399	1.610	12/08/21	165		100	1.610	AUS
19626414	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	17399	1.610	12/08/21	193		100	1.610	AUS
19626414	CHECK CONDITION OF PAINT AND DECALS	17399	1.610	12/08/21	435		100	1.610	AUS
19626414	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17399	1.610	12/08/21	530		100	1.610	AUS
19626414	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	17399	1.610	12/08/21	563		100	1.610	AUS
19626414	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	17399	1.610	12/08/21	605		100	1.610	AUS
19626414	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	17399	1.610	12/08/21	636		100	1.610	AUS
19626414	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	17399	1.610	12/08/21	637		100	1.610	AUS
19626414	GEN 6 PCON DECAL REPLACEMENT CHECKED	17399	1.610	12/08/21	647		100	1.610	AUS
19626414	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	17399	1.610	12/08/21	653		100	1.610	AUS
19626414	safety and function check	17399	1.610	12/08/21	9999999		100	1.610	AUS
19557728	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	19249	61.900	11/17/21	530		100	61.900	AUS
19557728	Replaced PCON	19249	61.900	11/17/21	9999999		150	61.900	AUS
19557696	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	19249	61.000	11/10/21	530		100	61.000	AUS
19557696	PCON on order	19249	61.000	11/10/21	9999999		150	61.000	AUS
19490736	LOCK OUT TAG DOWN EQUIP	18539	58.300	10/19/21	164		100	58.300	AU2
19490736	EQUIP LOCK OUT HAS BEEN REMOVED	18539	58.300	10/19/21	165		100	58.300	AU2
19490736	CHECK CONDITION OF PAINT AND DECALS	18539	58.300	10/19/21	435		100	58.300	AU2
19490736	ANNUAL INSPECTION *(USE AERIAL INSPECTION FORM)*	18539	58.300	10/19/21	459		100	58.300	AU2
19490736	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18539	58.300	10/19/21	530		100	58.300	AU2
19490736	completed 90 day	18539	58.300	10/19/21	9999999		150	58.300	AU2
19244719	wrong unit	18529	54.200	7/28/21	9999999		150	54.200	BWP
19143053	CHECK CONDITION OF PAINT AND DECALS	18539	54.200	6/22/21	435		100	54.200	AU2
19143053	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18539	54.200	6/22/21	530		100	54.200	AU2
19143053	completed 90 day unit checked out good	18539	54.200	6/22/21	9999999		150	54.200	AU2
18816116	CHANGE HYDRAULIC FLUID	17399	51.200	3/09/21	29		100	51.200	AUS
18816116	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	17399	51.200	3/09/21	34		100	51.200	AUS
18816116	LOCK OUT TAG DOWN EQUIP	17399	51.200	3/09/21	164		100	51.200	AUS
18816116	EQUIP LOCK OUT HAS BEEN REMOVED	17399	51.200	3/09/21	165		100	51.200	AUS
18816116	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	17399	51.200	3/09/21	193		100	51.200	AUS
18816116	CHECK CONDITION OF PAINT AND DECALS	17399	51.200	3/09/21	435		100	51.200	AUS
18816116	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17399	51.200	3/09/21	530		100	51.200	AUS
18816116	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	17399	51.200	3/09/21	563		100	51.200	AUS
18816116	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	17399	51.200	3/09/21	605		100	51.200	AUS
18816116	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	17399	51.200	3/09/21	636		100	51.200	AUS
18816116	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	17399	51.200	3/09/21	637		100	51.200	AUS
18816116	GEN 6 PCON DECAL REPLACEMENT CHECKED	17399	51.200	3/09/21	647		100	51.200	AUS
18816116	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	17399	51.200	3/09/21	653		100	51.200	AUS
18816116	safety and function check	17399	51.200	3/09/21	9999999		100	51.200	AUS
18792829	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18539	51.000	2/23/21	530		100	51.000	AU2
18792829	90 day inspection completed	18539	51.000	2/23/21	9999999		150	51.000	AU2

9/26/22 9:44:04

System: SUNSTATE

Equipment: 166355

Equipment Maintenance History

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

Cmpy: SS

Page: 18

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
18413354	LOCK OUT TAG DOWN EQUIP	16414	46.700	10/19/20	164		100	46.700	AU2
18413354	EQUIP LOCK OUT HAS BEEN REMOVED	16414	46.700	10/19/20	165		100	46.700	AU2
18413354	CHECK CONDITION OF PAINT AND DECALS	16414	46.700	10/19/20	435		100	46.700	AU2
18413354	ANNUAL INSPECTION *(USE AERIAL INSPECTION FORM)*	16414	46.700	10/19/20	459		100	46.700	AU2
18413354	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16414	46.700	10/19/20	530		100	46.700	AU2
18413354	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16414	46.700	10/19/20	563		100	46.700	AU2
18413354	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16414	46.700	10/19/20	636		100	46.700	AU2
18413354	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16414	46.700	10/19/20	637		100	46.700	AU2
18413354	GEN 6 PCON DECAL REPLACEMENT CHECKED	16414	46.700	10/19/20	647		100	46.700	AU2
18413354	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16414	46.700	10/19/20	653		100	46.700	AU2
18413354	completed annual needs ansi decal	16414	46.700	10/19/20	9999999		210	46.700	AU2
18413354	completed annual	16414	46.700	10/19/20	9999999		210	46.700	AU2
18346406	LOCK OUT TAG DOWN EQUIP	16414	46.700	9/21/20	164		100	46.700	AU2
18346406	EQUIP LOCK OUT HAS BEEN REMOVED	16414	46.700	9/21/20	165		100	46.700	AU2
18346406	CHECK CONDITION OF PAINT AND DECALS	16414	46.700	9/21/20	435		100	46.700	AU2
18346406	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16414	46.700	9/21/20	530		100	46.700	AU2
18346406	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16414	46.700	9/21/20	563		100	46.700	AU2
18346406	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	16414	46.700	9/21/20	605		100	46.700	AU2
18346406	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16414	46.700	9/21/20	636		100	46.700	AU2
18346406	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16414	46.700	9/21/20	637		100	46.700	AU2
18346406	GEN 6 PCON DECAL REPLACEMENT CHECKED	16414	46.700	9/21/20	647		100	46.700	AU2
18346406	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16414	46.700	9/21/20	653		100	46.700	AU2
18346406	replaced pcon board & griptape	16414	46.700	9/21/20	9999999		100	46.700	AU2
18343731	PCon Needs to be Replaced	17442	40.000	9/10/20	9999999		150	40.000	AU2
18337943	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17130	40.000	9/08/20	530		100	40.000	AU2
18337943	swapped back and tested	17130	40.000	9/08/20	9999999		150	40.000	AU2
18084198	LOCK OUT TAG DOWN EQUIP	14615	40.000	6/11/20	164		100	40.000	AU2
18084198	EQUIP LOCK OUT HAS BEEN REMOVED	14615	40.000	6/11/20	165		100	40.000	AU2
18084198	CHECK CONDITION OF PAINT AND DECALS	14615	40.000	6/11/20	435		100	40.000	AU2
18084198	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14615	40.000	6/11/20	530		100	40.000	AU2
18084198	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	14615	40.000	6/11/20	563		100	40.000	AU2
18084198	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	14615	40.000	6/11/20	636		100	40.000	AU2
18084198	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	14615	40.000	6/11/20	637		100	40.000	AU2
18084198	GEN 6 PCON DECAL REPLACEMENT CHECKED	14615	40.000	6/11/20	647		100	40.000	AU2
18084198	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	14615	40.000	6/11/20	653		100	40.000	AU2
18033543	LOCK OUT TAG DOWN EQUIP	16414	38.500	5/28/20	164		100	38.500	AU2
18033543	EQUIP LOCK OUT HAS BEEN REMOVED	16414	38.500	5/28/20	165		100	38.500	AU2
18033543	CHECK CONDITION OF PAINT AND DECALS	16414	38.500	5/28/20	435		100	38.500	AU2
18033543	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16414	38.500	5/28/20	530		100	38.500	AU2
18033543	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16414	38.500	5/28/20	563		100	38.500	AU2
18033543	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16414	38.500	5/28/20	636		100	38.500	AU2
18033543	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16414	38.500	5/28/20	637		100	38.500	AU2
18033543	GEN 6 PCON DECAL REPLACEMENT CHECKED	16414	38.500	5/28/20	647		100	38.500	AU2
18033543	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16414	38.500	5/28/20	653		100	38.500	AU2
17867850	LOCK OUT TAG DOWN EQUIP	15769	31.000	3/26/20	164		100	31.000	AU2
17867850	EQUIP LOCK OUT HAS BEEN REMOVED	15769	31.000	3/26/20	165		100	31.000	AU2
17867850	CHECK CONDITION OF PAINT AND DECALS	15769	31.000	3/26/20	435		100	31.000	AU2
17867850	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15769	31.000	3/26/20	530		100	31.000	AU2
17867850	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15769	31.000	3/26/20	563		100	31.000	AU2
17867850	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15769	31.000	3/26/20	636		100	31.000	AU2
17867850	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15769	31.000	3/26/20	637		100	31.000	AU2
17867850	GEN 6 PCON DECAL REPLACEMENT CHECKED	15769	31.000	3/26/20	647		100	31.000	AU2
17867850	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15769	31.000	3/26/20	653		100	31.000	AU2

9/26/22 9:44:04

System: SUNSTATE

Equipment: 166355

Equipment Maintenance History

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

Cmpy: SS

Page: 19

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
17830580	LOCK OUT TAG DOWN EQUIP	18019	29.200	3/17/20	164		100	29.200	AU2
17830580	EQUIP LOCK OUT HAS BEEN REMOVED	18019	29.200	3/17/20	165		100	29.200	AU2
17830580	CHECK CONDITION OF PAINT AND DECALS	18019	29.200	3/17/20	435		100	29.200	AU2
17830580	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18019	29.200	3/17/20	530		100	29.200	AU2
17830580	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18019	29.200	3/17/20	563		100	29.200	AU2
17830580	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18019	29.200	3/17/20	636		100	29.200	AU2
17830580	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18019	29.200	3/17/20	637		100	29.200	AU2
17830580	GEN 6 PCON DECAL REPLACEMENT CHECKED	18019	29.200	3/17/20	647		100	29.200	AU2
17830580	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	18019	29.200	3/17/20	653		100	29.200	AU2
17830580	replaced damaged component	18019	29.200	3/17/20	9999999		100	29.200	AU2
17766620	EQUIP LOCK OUT HAS BEEN REMOVED	15765	25.200	2/20/20	165		100	25.200	AU2
17766620	CHECK CONDITION OF PAINT AND DECALS	15765	25.200	2/20/20	435		100	25.200	AU2
17766620	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15765	25.200	2/20/20	530		100	25.200	AU2
17766620	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15765	25.200	2/20/20	563		100	25.200	AU2
17766620	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15765	25.200	2/20/20	636		100	25.200	AU2
17766620	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15765	25.200	2/20/20	637		100	25.200	AU2
17766620	GEN 6 PCON DECAL REPLACEMENT CHECKED	15765	25.200	2/20/20	647		100	25.200	AU2
17766620	replaced control box tested it and it works good	15765	25.200	2/20/20	9999999		150	25.200	AU2
17682892	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	13193	24.600	2/07/20	34		100	24.600	AUS
17682892	LOCK OUT TAG DOWN EQUIP	13193	24.600	2/07/20	164		100	24.600	AUS
17682892	EQUIP LOCK OUT HAS BEEN REMOVED	13193	24.600	2/07/20	165		100	24.600	AUS
17682892	CHECK CONDITION OF PAINT AND DECALS	13193	24.600	2/07/20	435		100	24.600	AUS
17682892	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	13193	24.600	2/07/20	530		100	24.600	AUS
17682892	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	13193	24.600	2/07/20	563		100	24.600	AUS
17682892	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	13193	24.600	2/07/20	605		100	24.600	AUS
17682892	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	13193	24.600	2/07/20	636		100	24.600	AUS
17682892	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	13193	24.600	2/07/20	637		100	24.600	AUS
17682892	GEN 6 PCON DECAL REPLACEMENT CHECKED	13193	24.600	2/07/20	647		100	24.600	AUS
17682892	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	13193	24.600	2/07/20	653		100	24.600	AUS
17682892	Could not duplicate, checked drive motors and batt	13193	24.600	2/10/20	9999999		100	24.600	AUS
17681323	inspected unit and will be exchanged for faulty co	17085	32.300	1/22/20	9999999		150	32.300	AUS
17638618	Drop Off Key	16752	32.300	1/08/20	9999999		150	32.300	AUS
17424064	CHECK CONDITION OF PAINT AND DECALS	18157	32.300	10/22/19	435		100	32.300	AUS
17424064	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	32.300	10/22/19	530		100	32.300	AUS
17424064	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18157	32.300	10/22/19	563		100	32.300	AUS
17424064	Completed 90 Day Inspection	18157	32.300	10/22/19	9999999		150	32.300	AUS
17411262	CHECK CONDITION OF PAINT AND DECALS	18157	32.300	10/17/19	435		100	32.300	AUS
17411262	ANNUAL INSPECTION *(USE INSPECTION FORM)*	18157	32.300	10/17/19	459		100	32.300	AUS
17411262	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	32.300	10/17/19	530		100	32.300	AUS
17411262	Completed Annual Inspection	18157	32.300	10/17/19	9999999		150	32.300	AUS
17045362	CHECK CONDITION OF PAINT AND DECALS	18157	32.300	6/25/19	435		100	32.300	AUS
17045362	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	32.300	6/25/19	530		100	32.300	AUS
17045362	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18157	32.300	6/25/19	563		100	32.300	AUS
17045362	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18157	32.300	6/25/19	637		100	32.300	AUS
17045362	Completed 90 Day Safety Inspection	18157	32.300	6/25/19	9999999		150	32.300	AUS
16764197	CHECK CONDITION OF PAINT AND DECALS	15109	32.300	3/25/19	435		100	32.300	AUS
16764197	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15109	32.300	3/25/19	530		100	32.300	AUS
16764197	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15109	32.300	3/25/19	563		100	32.300	AUS
16764197	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	15109	32.300	3/25/19	605		100	32.300	AUS
16764197	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15109	32.300	3/25/19	636		100	32.300	AUS
16764197	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15109	32.300	3/25/19	637		100	32.300	AUS
16764197	GEN 6 PCON DECAL REPLACEMENT CHECKED	15109	32.300	3/25/19	647		100	32.300	AUS
16764197	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15109	32.300	3/25/19	653		100	32.300	AUS

9/26/22 9:44:04

System: SUNSTATE

Equipment: 166355

Equipment Maintenance History

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

Cmpy: SS

Page: 20

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
16764197	replaced clips	15109	32.300	3/25/19	9999999		100	32.300	AUS
16463572	CHANGE HYDRAULIC FLUID	13193	25.000	12/11/18	29		100	25.000	AUS
16463572	CHECK CONDITION OF PAINT AND DECALS	13193	25.000	12/11/18	435		100	25.000	AUS
16463572	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	13193	25.000	12/11/18	530		100	25.000	AUS
16463572	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	13193	25.000	12/11/18	563		100	25.000	AUS
16463572	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	13193	25.000	12/11/18	636		100	25.000	AUS
16463572	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	13193	25.000	12/11/18	637		100	25.000	AUS
16463572	GEN 6 PCON DECAL REPLACEMENT CHECKED	13193	25.000	12/11/18	647		100	25.000	AUS
16463572	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	13193	25.000	12/11/18	653		100	25.000	AUS
16463572	Replaced hyd. power unit.	13193	25.000	12/11/18	9999999		210	25.000	AUS
16251572	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	15769	24.000	9/20/18	34		100	24.000	AU2
16251572	CHECK CONDITION OF PAINT AND DECALS	15769	24.000	9/20/18	435		100	24.000	AU2
16251572	ANNUAL INSPECTION *(USE INSPECTION FORM)*	15769	24.000	9/20/18	459		100	24.000	AU2
16251572	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15769	24.000	9/20/18	530		100	24.000	AU2
16251572	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15769	24.000	9/20/18	563		100	24.000	AU2
16251572	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	15769	24.000	9/20/18	605		100	24.000	AU2
16251572	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15769	24.000	9/20/18	636		100	24.000	AU2
16251572	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15769	24.000	9/20/18	637		100	24.000	AU2
16251572	GEN 6 PCON DECAL REPLACEMENT CHECKED	15769	24.000	9/20/18	647		100	24.000	AU2
16251572	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15769	24.000	9/20/18	653		100	24.000	AU2
16247994	*WARRANTY-MACHINE & ENGINE OR ELECTRIC MOTOR 1YR	15765	24.000	9/19/18	2		100	24.000	AU2
16247994	CHECK CONDITION OF PAINT AND DECALS	15765	24.000	9/19/18	435		100	24.000	AU2
16247994	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15765	24.000	9/19/18	530		100	24.000	AU2
16247994	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15765	24.000	9/19/18	563		100	24.000	AU2
16247994	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15765	24.000	9/19/18	636		100	24.000	AU2
16247994	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15765	24.000	9/19/18	637		100	24.000	AU2
16247994	GEN 6 PCON DECAL REPLACEMENT CHECKED	15765	24.000	9/19/18	647		100	24.000	AU2
16247994	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15765	24.000	9/19/18	653		100	24.000	AU2
16247994	unit charged in shop. 28.4volts RESET PRESSURES ON	15765	24.000	9/25/18	9999999		100	24.000	AU2
16246148	ready for pick up	15765	14.200	9/18/18	9999999		150	14.200	AU2
16220653	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16778	14.200	9/10/18	530		100	14.200	AUS
16220653	Complete 90 day	16778	14.200	9/10/18	9999999		150	14.200	AUS
15957149	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16778	9.600	6/11/18	530		100	9.600	AUS
15957149	Complete 90 day	16778	9.600	6/11/18	9999999		150	9.600	AUS
15659017	CHECK CONDITION OF PAINT AND DECALS	16057	2.400	2/27/18	435		100	2.400	KLN
15659017	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16057	2.400	2/27/18	530		100	2.400	KLN
15659017	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16057	2.400	2/27/18	563		100	2.400	KLN
15659017	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	16057	2.400	2/27/18	605		100	2.400	KLN
15659017	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16057	2.400	2/27/18	636		100	2.400	KLN
15659017	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16057	2.400	2/27/18	637		100	2.400	KLN
15659017	GEN 6 PCON DECAL REPLACEMENT CHECKED	16057	2.400	2/27/18	647		100	2.400	KLN
15659017	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16057	2.400	2/27/18	653		100	2.400	KLN
15522064	CHECK CONDITION OF PAINT AND DECALS	16042	.300	1/09/18	435		100	.300	KLN
15522064	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16042	.300	1/09/18	530		100	.300	KLN
15522064	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16042	.300	1/09/18	563		100	.300	KLN
15522064	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16042	.300	1/09/18	636		100	.300	KLN
15522064	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16042	.300	1/09/18	637		100	.300	KLN
15522064	GEN 6 PCON DECAL REPLACEMENT CHECKED	16042	.300	1/09/18	647		100	.300	KLN
15522064	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16042	.300	1/09/18	653		100	.300	KLN
15522064	inspection complete	16042	.300	1/09/18	9999999		150	.300	KLN
15261037	CHECK CONDITION OF PAINT AND DECALS	14577	.300	10/07/17	435		100	.300	AUS
15261037	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14577	.300	10/07/17	530		100	.300	AUS
15261037	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	14577	.300	10/07/17	563		100	.300	AUS

9/26/22 9:44:04
System: SUNSTATE
Equipment: 166355

Equipment Maintenance History

Cmpy: SS
Page: 21
- 99/99/99

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
15261037	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	14577	.300	10/07/17	636		100	.300	AUS
15261037	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	14577	.300	10/07/17	637		100	.300	AUS
15261037	GEN 6 PCON DECAL REPLACEMENT CHECKED	14577	.300	10/07/17	647		100	.300	AUS
15261037	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	14577	.300	10/07/17	653		100	.300	AUS
15261037	Warranty. Blue Loctite emerg down cable screw to d	14577	.300	10/07/17	9999999		210	.300	AUS
15138621	CHECK CONDITION OF PAINT AND DECALS	13289	.200	8/28/17	435		100	.200	AUS
15138621	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	13289	.200	8/28/17	530		100	.200	AUS
15138621	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	13289	.200	8/28/17	563		100	.200	AUS
15138621	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	13289	.200	8/28/17	636		100	.200	AUS
15138621	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	13289	.200	8/28/17	637		100	.200	AUS
15138621	GEN 6 PCON DECAL REPLACEMENT CHECKED	13289	.200	8/28/17	647		100	.200	AUS
15138621	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	13289	.200	8/28/17	653		100	.200	AUS

Total labor hours:

Total extended amount:

\$.00

*** End of report ***