

9/26/22 9:44:17
System: SUNSTATE
Equipment: 166444

Equipment Maintenance History

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

Cmpy: SS
Page: 1
- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
19845966	LOCK OUT TAG DOWN EQUIP	18157	88.300	3/04/22	164		100	88.300	AUS
19845966	EQUIP LOCK OUT HAS BEEN REMOVED	18157	88.300	3/04/22	165		100	88.300	AUS
19845966	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	18157	88.300	3/04/22	193		100	88.300	AUS
19845966	CHECK CONDITION OF PAINT AND DECALS	18157	88.300	3/04/22	435		100	88.300	AUS
19845966	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	88.300	3/04/22	530		100	88.300	AUS
19845966	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18157	88.300	3/04/22	563		100	88.300	AUS
19845966	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18157	88.300	3/04/22	636		100	88.300	AUS
19845966	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18157	88.300	3/04/22	637		100	88.300	AUS
19845966	GEN 6 PCON DECAL REPLACEMENT CHECKED	18157	88.300	3/04/22	647		100	88.300	AUS
19845966	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	18157	88.300	3/04/22	653		100	88.300	AUS
19845966	Cleared Debris From Pothole Guard	18157	88.300	3/04/22	9999999		100	88.300	AUS
19575976	CHANGE HYDRAULIC FLUID	17399	87.800	12/07/21	29		100	87.800	AUS
19575976	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	17399	87.800	12/07/21	34		100	87.800	AUS
19575976	LOCK OUT TAG DOWN EQUIP	17399	87.800	12/07/21	164		100	87.800	AUS
19575976	EQUIP LOCK OUT HAS BEEN REMOVED	17399	87.800	12/07/21	165		100	87.800	AUS
19575976	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	17399	87.800	12/07/21	193		100	87.800	AUS
19575976	CHECK CONDITION OF PAINT AND DECALS	17399	87.800	12/07/21	435		100	87.800	AUS
19575976	ANNUAL INSPECTION *(USE AERIAL INSPECTION FORM)*	17399	87.800	12/07/21	459		100	87.800	AUS
19575976	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17399	87.800	12/07/21	530		100	87.800	AUS
19575976	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	17399	87.800	12/07/21	563		100	87.800	AUS
19575976	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	17399	87.800	12/07/21	605		100	87.800	AUS
19575976	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	17399	87.800	12/07/21	636		100	87.800	AUS
19575976	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	17399	87.800	12/07/21	637		100	87.800	AUS
19575976	GEN 6 PCON DECAL REPLACEMENT CHECKED	17399	87.800	12/07/21	647		100	87.800	AUS
19575976	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	17399	87.800	12/07/21	653		100	87.800	AUS
19575976	safety and function check	17399	87.800	12/07/21	9999999		100	87.800	AUS
19567753	Installed 10A fuse to move unit, see comments	19249	80.000	11/15/21	9999999		150	80.000	AUS
19490761	LOCK OUT TAG DOWN EQUIP	18539	86.200	10/19/21	164		100	86.200	AU2
19490761	EQUIP LOCK OUT HAS BEEN REMOVED	18539	86.200	10/19/21	165		100	86.200	AU2
19490761	CHECK CONDITION OF PAINT AND DECALS	18539	86.200	10/19/21	435		100	86.200	AU2
19490761	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18539	86.200	10/19/21	530		100	86.200	AU2
19490761	completed 90 day	18539	86.200	10/19/21	9999999		150	86.200	AU2
19143541	CHECK CONDITION OF PAINT AND DECALS	18539	80.000	6/22/21	435		100	80.000	AU2
19143541	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18539	80.000	6/22/21	530		100	80.000	AU2
19143541	completed 90 day unit checked out good	18539	80.000	6/22/21	9999999		150	80.000	AU2
18630655	LOCK OUT TAG DOWN EQUIP	11671	80.000	2/11/21	164		100	80.000	AUS
18630655	EQUIP LOCK OUT HAS BEEN REMOVED	11671	80.000	2/11/21	165		100	80.000	AUS
18630655	INSPECT STEERING KNUCKLE THRUST WASHER IF EQUIPPED	11671	80.000	2/11/21	193		100	80.000	AUS
18630655	CHECK CONDITION OF PAINT AND DECALS	11671	80.000	2/11/21	435		100	80.000	AUS
18630655	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	11671	80.000	2/11/21	530		100	80.000	AUS
18630655	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	11671	80.000	2/11/21	563		100	80.000	AUS
18630655	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	11671	80.000	2/11/21	605		100	80.000	AUS
18630655	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	11671	80.000	2/11/21	636		100	80.000	AUS
18630655	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	11671	80.000	2/11/21	637		100	80.000	AUS
18630655	GEN 6 PCON DECAL REPLACEMENT CHECKED	11671	80.000	2/11/21	647		100	80.000	AUS
18630655	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	11671	80.000	2/11/21	653		100	80.000	AUS
18630655	send to paint shop	17399	80.000	2/11/21	9999999		100	80.000	AUS
18153695	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	18685	80.000	7/07/20	34		100	80.000	AUS
18153695	LOCK OUT TAG DOWN EQUIP	18685	80.000	7/07/20	164		100	80.000	AUS
18153695	EQUIP LOCK OUT HAS BEEN REMOVED	18685	80.000	7/07/20	165		100	80.000	AUS
18153695	CHECK CONDITION OF PAINT AND DECALS	18685	80.000	7/07/20	435		100	80.000	AUS
18153695	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18685	80.000	7/07/20	530		100	80.000	AUS
18153695	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18685	80.000	7/07/20	563		100	80.000	AUS

9/26/22 9:44:17

Equipment Maintenance History

Cmpy: SS

System: SUNSTATE

Page: 2

Equipment: 166444

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
18153695	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18685	80.000	7/07/20	636		100	80.000	AUS
18153695	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18685	80.000	7/07/20	637		100	80.000	AUS
18153695	GEN 6 PCON DECAL REPLACEMENT CHECKED	18685	80.000	7/07/20	647		100	80.000	AUS
18153695	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	18685	80.000	7/07/20	653		100	80.000	AUS
18040426	LOCK OUT TAG DOWN EQUIP	15109	72.500	5/28/20	164		100	72.500	AUS
18040426	EQUIP LOCK OUT HAS BEEN REMOVED	15109	72.500	5/28/20	165		100	72.500	AUS
18040426	CHECK CONDITION OF PAINT AND DECALS	15109	72.500	5/28/20	435		100	72.500	AUS
18040426	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15109	72.500	5/28/20	530		100	72.500	AUS
18040426	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15109	72.500	5/28/20	563		100	72.500	AUS
18040426	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15109	72.500	5/28/20	636		100	72.500	AUS
18040426	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15109	72.500	5/28/20	637		100	72.500	AUS
18040426	GEN 6 PCON DECAL REPLACEMENT CHECKED	15109	72.500	5/28/20	647		100	72.500	AUS
18040426	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15109	72.500	5/28/20	653		100	72.500	AUS
18040426	removed concrete debris and splatter, replaced cov	15109	72.500	5/28/20	9999999		100	72.500	AUS
17961691	LOCK OUT TAG DOWN EQUIP	18775	68.300	4/29/20	164		100	68.300	AUS
17961691	EQUIP LOCK OUT HAS BEEN REMOVED	18775	68.300	4/29/20	165		100	68.300	AUS
17961691	CHECK CONDITION OF PAINT AND DECALS	18775	68.300	4/29/20	435		100	68.300	AUS
17961691	ANNUAL INSPECTION *(USE AERIAL INSPECTION FORM)*	18775	68.300	4/29/20	459		100	68.300	AUS
17961691	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18775	68.300	4/29/20	530		100	68.300	AUS
17961691	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18775	68.300	4/29/20	563		100	68.300	AUS
17961691	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18775	68.300	4/29/20	636		100	68.300	AUS
17961691	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18775	68.300	4/29/20	637		100	68.300	AUS
17961691	GEN 6 PCON DECAL REPLACEMENT CHECKED	18775	68.300	4/29/20	647		100	68.300	AUS
17961691	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	18775	68.300	4/29/20	653		100	68.300	AUS
17681916	order and replace wheels	14436	61.000	2/14/20	9999999		100	61.000	AUS
17455485	CHANGE HYDRAULIC FLUID	14436	61.000	1/13/20	29		100	61.000	AUS
17455485	LOCK OUT TAG DOWN EQUIP	14436	61.000	1/13/20	164		100	61.000	AUS
17455485	EQUIP LOCK OUT HAS BEEN REMOVED	14436	61.000	1/13/20	165		100	61.000	AUS
17455485	CHECK CONDITION OF PAINT AND DECALS	14436	61.000	1/13/20	435		100	61.000	AUS
17455485	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14436	61.000	1/13/20	530		100	61.000	AUS
17455485	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	14436	61.000	1/13/20	563		100	61.000	AUS
17455485	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	14436	61.000	1/13/20	605		100	61.000	AUS
17455485	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	14436	61.000	1/13/20	636		100	61.000	AUS
17455485	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	14436	61.000	1/13/20	637		100	61.000	AUS
17455485	GEN 6 PCON DECAL REPLACEMENT CHECKED	14436	61.000	1/13/20	647		100	61.000	AUS
17455485	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	14436	61.000	1/13/20	653		100	61.000	AUS
17455485	calibrate joystick	14436	61.000	1/13/20	9999999		100	61.000	AUS
17453972	Recalibrated PCU Joystick to Allow Extraction/ Uni	16752	61.000	10/31/19	9999999		150	61.000	AUS
17436528	R&R pump motor and coupler. tested to ensure oper	17085	41.500	10/28/19	9999999		150	41.500	AUS
17436475	order new pump motor	17085	41.500	10/25/19	9999999		150	41.500	AUS
17402800	CHECK CONDITION OF PAINT AND DECALS	16752	41.500	10/15/19	435		100	41.500	AUS
17402800	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16752	41.500	10/15/19	530		100	41.500	AUS
17402800	Reset GCON Estop to Display Full Charge/ Verify Ch	16752	41.500	10/15/19	9999999		150	41.500	AUS
17132335	CHECK CONDITION OF PAINT AND DECALS	18157	19.000	7/23/19	435		100	19.000	AUS
17132335	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	19.000	7/23/19	530		100	19.000	AUS
17132335	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18157	19.000	7/23/19	563		100	19.000	AUS
17132335	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18157	19.000	7/23/19	636		100	19.000	AUS
17132335	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18157	19.000	7/23/19	637		100	19.000	AUS
17132335	GEN 6 PCON DECAL REPLACEMENT CHECKED	18157	19.000	7/23/19	647		100	19.000	AUS
17132335	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	18157	19.000	7/23/19	653		100	19.000	AUS
17037169	CHANGE HYDRAULIC FILTERS(FILTERS ONLY NOT OIL)	15769	13.800	6/27/19	34		100	13.800	AU2
17037169	CHECK CONDITION OF PAINT AND DECALS	15769	13.800	6/27/19	435		100	13.800	AU2
17037169	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15769	13.800	6/27/19	530		100	13.800	AU2

9/26/22 9:44:17

Equipment Maintenance History

Cmpy: SS

System: SUNSTATE

Page: 3

Equipment: 166444

Cat/Class: 55-5780

SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
17037169	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15769	13.800	6/27/19	563		100	13.800	AU2
17037169	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	15769	13.800	6/27/19	605		100	13.800	AU2
17037169	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15769	13.800	6/27/19	636		100	13.800	AU2
17037169	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15769	13.800	6/27/19	637		100	13.800	AU2
17037169	GEN 6 PCON DECAL REPLACEMENT CHECKED	15769	13.800	6/27/19	647		100	13.800	AU2
17037169	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15769	13.800	6/27/19	653		100	13.800	AU2
17037169	REPLACED CHARGER PLUG	15769	13.800	6/27/19	9999999		100	13.800	AU2
17025904	CHECK CONDITION OF PAINT AND DECALS	18157	49.400	6/18/19	435		100	49.400	AUS
17025904	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	18157	49.400	6/18/19	530		100	49.400	AUS
17025904	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	18157	49.400	6/18/19	563		100	49.400	AUS
17025904	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	18157	49.400	6/18/19	636		100	49.400	AUS
17025904	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	18157	49.400	6/18/19	637		100	49.400	AUS
17025904	GEN 6 PCON DECAL REPLACEMENT CHECKED	18157	49.400	6/18/19	647		100	49.400	AUS
17025904	Completed 90 Day Inspection	18157	49.400	6/18/19	9999999		150	49.400	AUS
16992296	REplace strob light and guard	16190	49.400	6/17/19	9999999		140	49.400	AUS
16965861	Parts order	16190	49.400	6/19/19	9999999		140	49.400	AUS
16852612	replaced charger cord	15765	49.400	4/23/19	9999999		150	49.400	AU2
16635250	ANNUAL INSPECTION *(USE INSPECTION FORM)*	16190	49.400	2/06/19	459		100	49.400	AUS
16635250	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16190	49.400	2/06/19	530		100	49.400	AUS
16635250	Annual inspection completed	16190	49.400	2/06/19	9999999		150	49.400	AUS
16513657	CHECK CONDITION OF PAINT AND DECALS	17085	49.400	12/19/18	435		100	49.400	AUS
16513657	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17085	49.400	12/19/18	530		100	49.400	AUS
16513657	performed check service	17085	49.400	12/19/18	9999999		150	49.400	AUS
16223794	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15765	56.400	9/11/18	530		100	56.400	AU2
16223794	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15765	56.400	9/11/18	636		100	56.400	AU2
16223794	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15765	56.400	9/11/18	637		100	56.400	AU2
16223794	GEN 6 PCON DECAL REPLACEMENT CHECKED	15765	56.400	9/11/18	647		100	56.400	AU2
16223794	tested all functions unit is working good/will nee	15765	56.400	9/11/18	9999999		150	56.400	AU2
15948007	CHECK CONDITION OF PAINT AND DECALS	17193	40.400	6/08/18	435		100	40.400	SAA
15948007	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17193	40.400	6/08/18	530		100	40.400	SAA
15948007	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	17193	40.400	6/08/18	563		100	40.400	SAA
15948007	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	17193	40.400	6/08/18	636		100	40.400	SAA
15948007	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	17193	40.400	6/08/18	637		100	40.400	SAA
15948007	GEN 6 PCON DECAL REPLACEMENT CHECKED	17193	40.400	6/08/18	647		100	40.400	SAA
15948007	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	17193	40.400	6/08/18	653		100	40.400	SAA
15878859	CHECK CONDITION OF PAINT AND DECALS	17430	35.800	5/15/18	435		100	35.800	SAA
15878859	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17430	35.800	5/15/18	530		100	35.800	SAA
15878859	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	17430	35.800	5/15/18	563		100	35.800	SAA
15878859	INSPECT ELECTRIC MOTOR BRUSHES, REPLACE AS NEEDED	17430	35.800	5/15/18	605		100	35.800	SAA
15878859	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	17430	35.800	5/15/18	636		100	35.800	SAA
15878859	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	17430	35.800	5/15/18	637		100	35.800	SAA
15878859	GEN 6 PCON DECAL REPLACEMENT CHECKED	17430	35.800	5/15/18	647		100	35.800	SAA
15878859	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	17430	35.800	5/15/18	653		100	35.800	SAA
15808982	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	17328	34.300	4/19/18	530		100	34.300	SAA
15808982	completed inspection	17328	34.300	4/19/18	9999999		150	34.300	SAA
15529806	CHECK CONDITION OF PAINT AND DECALS	15929	17.500	1/15/18	435		100	17.500	SAA
15529806	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	15929	17.500	1/15/18	530		100	17.500	SAA
15529806	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	15929	17.500	1/15/18	563		100	17.500	SAA
15529806	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	15929	17.500	1/15/18	636		100	17.500	SAA
15529806	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	15929	17.500	1/15/18	637		100	17.500	SAA
15529806	GEN 6 PCON DECAL REPLACEMENT CHECKED	15929	17.500	1/15/18	647		100	17.500	SAA
15529806	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	15929	17.500	1/15/18	653		100	17.500	SAA
15529806	check service	15929	17.500	1/15/18	9999999		210	17.500	SAA

9/26/22 9:44:17

Equipment Maintenance History

Cmpy: SS

System: SUNSTATE

Page: 4

Equipment: 166444

Cat/Class: 55-5780 SCISSOR LIFT-13' 2WD ELECTRIC

Status: A From/To date:

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
15526262	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14599	17.200	1/10/18	530		100	17.200	SAA
15526262	DRIVER INSPECTION	14599	17.200	1/10/18	9999999		100	17.200	SAA
15486675	CHECK CONDITION OF PAINT AND DECALS	16039	17.200	12/26/17	435		100	17.200	SAA
15486675	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16039	17.200	12/26/17	530		100	17.200	SAA
15486675	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	16039	17.200	12/26/17	563		100	17.200	SAA
15486675	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	16039	17.200	12/26/17	636		100	17.200	SAA
15486675	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	16039	17.200	12/26/17	637		100	17.200	SAA
15486675	GEN 6 PCON DECAL REPLACEMENT CHECKED	16039	17.200	12/26/17	647		100	17.200	SAA
15486675	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	16039	17.200	12/26/17	653		100	17.200	SAA
15461027	CHECK CONDITION OF PAINT AND DECALS	13673	17.200	12/14/17	435		100	17.200	SAA
15461027	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	13673	17.200	12/14/17	530		100	17.200	SAA
15461027	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	13673	17.200	12/14/17	563		100	17.200	SAA
15461027	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	13673	17.200	12/14/17	636		100	17.200	SAA
15461027	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	13673	17.200	12/14/17	637		100	17.200	SAA
15461027	GEN 6 PCON DECAL REPLACEMENT CHECKED	13673	17.200	12/14/17	647		100	17.200	SAA
15461027	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	13673	17.200	12/14/17	653		100	17.200	SAA
15296909	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16974	.010	10/19/17	530		100	.010	SAA
15296909	add loctite	16974	.010	10/19/17	9999999		210	.010	SAA
15286024	CHECK CONDITION OF PAINT AND DECALS	16974	.010	10/16/17	435		100	.010	SAA
15286024	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	16974	.010	10/16/17	530		100	.010	SAA
15286024	apply loctite to safety release valve cord nut	16974	.010	10/16/17	9999999		150	.010	SAA
15286024	apply locktite	16974	.010	10/16/17	9999999		150	.010	SAA
15249305	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14599	.010	10/04/17	530		100	.010	SAA
15249305	DRIVER INSPECTION	14599	.010	10/04/17	9999999		100	.010	SAA
15147293	CHECK CONDITION OF PAINT AND DECALS	14432	.010	8/30/17	435		100	.010	SAA
15147293	SAFETY, 90 DAY, ROUTINE MAINTENANCE INSPECTION	14432	.010	8/30/17	530		100	.010	SAA
15147293	CHECK/INSTALL STATIC GROUND STRAP IF NEEDED	14432	.010	8/30/17	563		100	.010	SAA
15147293	CHECK CHARGER INTERLOCK SYS/SERV BULLETIN 9/30/11	14432	.010	8/30/17	636		100	.010	SAA
15147293	CHECK CONTROL BOX SECUREMENT(WORKING PROPERLY)	14432	.010	8/30/17	637		100	.010	SAA
15147293	GEN 6 PCON DECAL REPLACEMENT CHECKED	14432	.010	8/30/17	647		100	.010	SAA
15147293	RETORQUE WHEEL LUG NUTS/BOLTS TO MANUFACTURE SPEC.	14432	.010	8/30/17	653		100	.010	SAA
15147293	performed make ready	14432	.010	8/31/17	9999999		100	.010	SAA

Total labor hours:

Total extended amount:

\$.00

*** End of report ***