



Lubricant Analysis Report

North America: +1-877-808-3750
 Latin America: +1-317-808-3750 / +502-3093-6466 (WhatsApp)
 Europe: +1-317-808-3750

0	1	2	3	4
NORMAL	ABNORMAL	ABNORMAL	ABNORMAL	CRITICAL

Overall report severity based on comments.

Account Information		Component Information		Sample Information	
Account Number: 153995-0002-0000 Company Name: BOOM & BUCKET Contact: KRIS HUFF Address: 600 CONGRESS AVE AUSTIN, TX US Phone Number: 1888-313-1597		Component ID: 210K E Secondary ID: JALISCO PAVING Component Type: DIESEL ENGINE Manufacturer: JOHN DEERE Model: 4 CYL Application: UNKNOWN Sump Capacity:		Tracking Number: 22222W10910 Lab Number: S-865688 Lab Location: Salt Lake City Data Analyst: AC Sampled: 09-Sep-2022 Received: 21-Sep-2022 Completed: 22-Sep-2022	
Filter Information		Miscellaneous Information		Product Information	
Filter Type: Information Requested Micron Rating: 0				Product Manufacturer: Information Requested Product Name: Information Requested Viscosity Grade: Information Requested	
Comments		Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Aluminum is at a MINOR LEVEL; ALUMINUM sources in ENGINES include pistons, block and components (intake manifold, head, bearing caps), thrust bearings, main/rod bearing overlay or backing, alumina silica, or contamination from grease. Please provide missing lubricant information. Manufacturer, product name, and viscosity grade are needed to properly evaluate lubricant properties. Unit and/or lubricant TIME missing.			

Sample #	Wear Metals (ppm)										Contaminant Metals (ppm)			Multi-Source Metals (ppm)					Additive Metals (ppm)					
	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
1	11	1	0	2	2	1	1	0	0	0	3	2	1	0	59	0	0	0	5	921	1087	0	1052	1210

Sample Information									Contaminants			Fluid Properties				
Sample #	Date Sampled	Date Received	Lube Time	Unit Time	Lube Change	Lube Added	Filter Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100 °C	Acid Number	Base No. D4739	Oxidation	Nitration
			h	h	Lube Change	gal	Filter Change	%	%	%	cSt	cSt	mg KOH / g	mg KOH / g	abs / cm	abs / 0.1mm
1	09-Sep-2022	21-Sep-2022	0	0	Unk	0	Unk	<2 - Estimate	0.4 - E2412	<.1 - FTIR		14.2		7.86	9	6

Particle Count (particles/mL)										Additional Testing		
Sample #	ISO Code	> 4	> 6	> 10	> 14	> 21	> 38	> 70	> 100	Test Method		
	Based On	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL			
1	4/6/14	/ /										

Comments are advisory only and are based on the assumption that the sample and data submitted are valid. Results relate only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.