

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cmpy: SS

Page: 20

- 99/99/99

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
20576738	Bracket replaced by Asero 11/10	16219	35211.000	11/14/22	9999999		100	35211.000	AUS
20376558	ELD[6] Lights - All		35211.000	9/07/22	9999999		100	35211.000	AUS
20376558	replace with new	16219	35211.000	9/08/22	9999999		100	35211.000	AUS
20295194	REPLACED THE RFI TIRE WITH A GOOD SPARE	TIR	35211.000	8/09/22	9999999		100	35211.000	AU2
20225780	replace with new.	19173	35211.000	7/22/22	9999999		100	35211.000	AUS
20212495	ELD[7] Other		35211.000	7/12/22	9999999		100	35211.000	AUS
20212495	tighten bolts	16219	35211.000	7/15/22	9999999		100	35211.000	AUS
19957121	Added/programed new remote.	16219	35211.000	4/11/22	9999999		100	35211.000	AUS
19932601	replaced hyd hose	19173	35211.000	4/01/22	9999999		100	35211.000	AUS
19875638	REPLACED THE LEFT REAR INSIDE AND OUTSIDE TIRES	TIR	35211.000	3/11/22	9999999		100	35211.000	AUS
19745489	REPLACED 4 TIRES 10R17.5 SUMITOMO ST727	TIR	35211.000	1/25/22	9999999		100	35211.000	AUS
19710071	REPAIR RRO TIRE	TIR	35211.000	1/12/22	9999999		100	35211.000	AUS
19515225	replaced fittings	19173	35211.000	10/27/21	9999999		100	35211.000	AUS
19435879	replaced hose	19173	35211.000	9/30/21	9999999		100	35211.000	AUS
19359091	repaired by Dickenson	16219	35211.000	9/03/21	9999999		100	35211.000	AUS
19290749	REPAIR NAIL IN RRI TIRE	TIR	35211.000	8/12/21	9999999		100	35211.000	AUS
19270654	OSR-REPAIRED FLAT TIRE	99999	35211.000	8/05/21	9999999		100	35211.000	AUS
19270654	OSR-TECH FIXED FLAT TIRE ISSUES	99999	35211.000	8/05/21	9999999		100	35211.000	AUS
19269301	OSR-REPAIRED TIRE	99999	35211.000	8/05/21	9999999		100	35211.000	AUS
19269301	OSR-REMOVED SCREW AND PATCHED TIRE	99999	35211.000	8/05/21	9999999		100	35211.000	AUS
18898799	OSR-INSTALLED SPARES ON TRAILER	99999	35211.000	3/30/21	9999999		100	35211.000	AUS
18898799	OSR-REMOVED DAMAGED TIRES AND REPLACED WITH SPARES	99999	35211.000	3/30/21	9999999		100	35211.000	AUS
18891635	T&W RPLCD RRI RRO TRLR TIRES	TIR	35211.000	3/29/21	9999999		100	35211.000	AU2
18891106	2 REPLACEMENT RIMS ORDERED TO REPLACE DAMAGED RIMS	TIR	35211.000	3/29/21	9999999		100	35211.000	AU2
18701775	OSR-REPAIRED TIRES	99999	35211.000	1/19/21	9999999		100	35211.000	AUS
18701775	OSR-INSTALLED NEW VALVE STEMS ON TIRES. REPAIRED L	99999	35211.000	1/19/21	9999999		100	35211.000	AUS
18605382	INSTALL LOOSE NUT INDICATORS	TIR	35211.000	12/10/20	9999999		100	35211.000	AUS
18595845	OSR-REPAIRED FLAT TIRE	99999	35211.000	12/07/20	9999999		100	35211.000	AUS
18595845	OSR-PATCHED TIRE TO FIX THE FLAT	99999	35211.000	12/07/20	9999999		100	35211.000	AUS
18518788	OSR-REPAIRED THE TIRE \	99999	35211.000	11/09/20	9999999		100	35211.000	AUS
18518788	OSR-REMOVED LEAKY VALVE STEM AND REPLACED WITH A N	99999	35211.000	11/09/20	9999999		100	35211.000	AUS
18510106	OSR-TIRES GOOD TO GO	99999	35211.000	11/05/20	9999999		100	35211.000	AUS
18510106	OSR-INSTALLED NEW VALVE STEMS ON BOTH TIRES AND TE	99999	35211.000	11/05/20	9999999		100	35211.000	AUS
18301603	OSR-REPLACED TIRES	99999	35211.000	8/25/20	9999999		100	35211.000	AUS
18301603	OSR-LUGGED ON REPLACEMENT TIRES ON UNIT	99999	35211.000	8/25/20	9999999		100	35211.000	AUS
18282350	90 DAY BIT INSPECTION, (CALIFORNIA ONLY)	14436	35211.000	8/24/20	20		100	35211.000	AUS
18282350	LOCK OUT TAG DOWN EQUIP	14436	35211.000	8/24/20	164		100	35211.000	AUS
18282350	EQUIP LOCK OUT HAS BEEN REMOVED	14436	35211.000	8/24/20	165		100	35211.000	AUS
18282350	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	14436	35211.000	8/24/20	241		100	35211.000	AUS
18282350	SAFETY INSPECTION	14436	35211.000	8/24/20	242		100	35211.000	AUS
18282350	WARRANTY 1YR	14436	35211.000	8/24/20	255		210	35211.000	AUS
18282350	ANNUAL FEDERAL INSP. TRUCKS OVER 10,001 GVWR	14436	35211.000	8/24/20	352		100	35211.000	AUS
18282350	CHECK CONDITION OF PAINT AND DECALS	14436	35211.000	8/24/20	435		100	35211.000	AUS
18282350	GREASE AND ADJUST FIFTH WHEEL	14436	35211.000	8/24/20	446		100	35211.000	AUS
18282350	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	14436	35211.000	8/24/20	448		100	35211.000	AUS
18282350	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	14436	35211.000	8/24/20	449		100	35211.000	AUS
18282350	rebuilt brakes	14436	35211.000	8/24/20	9999999		100	35211.000	AUS
18235277	OSR-N/A CHARGED FOR SERVICE CALL	99999	35211.000	8/03/20	9999999		100	35211.000	AUS
18235277	OSR-NAIL DID NOT PUNCTURE TIRE	99999	35211.000	8/03/20	9999999		100	35211.000	AUS
18216365	REPLACE RRI/O TIRES W/NEW ST727 AND REPAIR LRO	TIR	35211.000	7/28/20	9999999		100	35211.000	AUS
18127519	1 TIRE INSTALLED FROM TIRE RACK	TIR	35211.000	6/25/20	9999999		100	35211.000	AUS
18115762	OSR-REPLACED TIRE	99999	35211.000	6/22/20	9999999		100	35211.000	AUS
18115762	OSR-TIRE REPLACED WITH A SPARE TIRE FROM THE YARD	99999	35211.000	6/22/20	9999999		100	35211.000	AUS

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cmpy: SS

Page: 21

- 99/99/99

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
17991134	OSR-REPAIRED TIRE	99999	35211.000	5/08/20	9999999		100	35211.000	AUS
17991134	OSR-REMOVED NAIL. PATCHED HOLE	99999	35211.000	5/08/20	9999999		100	35211.000	AUS
17700967	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	14436	35211.000	1/28/20	20		100	35211.000	AUS
17700967	LOCK OUT TAG DOWN EQUIP	14436	35211.000	1/28/20	164		100	35211.000	AUS
17700967	EQUIP LOCK OUT HAS BEEN REMOVED	14436	35211.000	1/28/20	165		100	35211.000	AUS
17700967	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	14436	35211.000	1/28/20	241		100	35211.000	AUS
17700967	SAFETY INSPECTION	14436	35211.000	1/28/20	242		100	35211.000	AUS
17700967	WARRANTY 1YR	14436	35211.000	1/28/20	255		210	35211.000	AUS
17700967	CHECK CONDITION OF PAINT AND DECALS	14436	35211.000	1/28/20	435		100	35211.000	AUS
17700967	GREASE AND ADJUST FIFTH WHEEL	14436	35211.000	1/28/20	446		100	35211.000	AUS
17700967	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	14436	35211.000	1/28/20	448		100	35211.000	AUS
17700967	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	14436	35211.000	1/28/20	449		100	35211.000	AUS
17700967	replace hydraulic hose and fitting	14436	35211.000	1/28/20	9999999		100	35211.000	AUS
17647954	REPLACED FRONT AXLE TIRES AND R/R/O	TIR	35211.000	1/10/20	9999999		100	35211.000	AUS
17641763	tighten caps and test	15109	35211.000	1/08/20	9999999		100	35211.000	AUS
17548208	OSR-REPAIRED TIRE	99999	35211.000	12/03/19	9999999		100	35211.000	AUS
17548208	OSR-PATCHED/PLUGGED TIRE	99999	35211.000	12/03/19	9999999		100	35211.000	AUS
17485209	LOCK OUT TAG DOWN EQUIP	14436	35211.000	11/16/19	164		100	35211.000	AUS
17485209	EQUIP LOCK OUT HAS BEEN REMOVED	14436	35211.000	11/16/19	165		100	35211.000	AUS
17485209	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	14436	35211.000	11/16/19	241		100	35211.000	AUS
17485209	SAFETY INSPECTION	14436	35211.000	11/16/19	242		100	35211.000	AUS
17485209	WARRANTY 1YR	14436	35211.000	11/16/19	255		210	35211.000	AUS
17485209	CHECK CONDITION OF PAINT AND DECALS	14436	35211.000	11/16/19	435		100	35211.000	AUS
17485209	GREASE AND ADJUST FIFTH WHEEL	14436	35211.000	11/16/19	446		100	35211.000	AUS
17485209	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	14436	35211.000	11/16/19	448		100	35211.000	AUS
17485209	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	14436	35211.000	11/16/19	449		100	35211.000	AUS
17485209	replace pin and cylinder	14436	35211.000	11/16/19	9999999		100	35211.000	AUS
17410135	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	14436	35211.000	10/17/19	20		100	35211.000	AUS
17410135	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	14436	35211.000	10/17/19	241		100	35211.000	AUS
17410135	SAFETY INSPECTION	14436	35211.000	10/17/19	242		100	35211.000	AUS
17410135	WARRANTY 1YR	14436	35211.000	10/17/19	255		210	35211.000	AUS
17410135	CHECK CONDITION OF PAINT AND DECALS	14436	35211.000	10/17/19	435		100	35211.000	AUS
17410135	GREASE AND ADJUST FIFTH WHEEL	14436	35211.000	10/17/19	446		100	35211.000	AUS
17410135	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	14436	35211.000	10/17/19	448		100	35211.000	AUS
17410135	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	14436	35211.000	10/17/19	449		100	35211.000	AUS
17410135	replace hose	14436	35211.000	10/17/19	9999999		100	35211.000	AUS
17230038	tightened spool cap bolts and test	15109	35211.000	8/21/19	9999999		100	35211.000	AUS
16892286	REPLACE RFO TIRE W/NEW DUE TO WEAR	TIR	35211.000	5/03/19	9999999		100	35211.000	AUS
16807159	will ck unit more thorough next week	15109	35211.000	4/05/19	9999999		100	35211.000	AUS
16793578	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	14615	35211.000	4/02/19	20		100	35211.000	AU2
16793578	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	14615	35211.000	4/02/19	241		100	35211.000	AU2
16793578	SAFETY INSPECTION	14615	35211.000	4/02/19	242		100	35211.000	AU2
16793578	WARRANTY 1YR	14615	35211.000	4/02/19	255		210	35211.000	AU2
16793578	REPACK WHEEL BEARINGS	15109	35211.000	5/01/19	315		100	35211.000	AUS
16793578	ANNUAL FEDERAL INSP. TRUCKS OVER 10,001 GVWR	15109	35211.000	5/01/19	352		100	35211.000	AUS
16793578	CHECK CONDITION OF PAINT AND DECALS	14615	35211.000	4/02/19	435		100	35211.000	AU2
16793578	GREASE AND ADJUST FIFTH WHEEL	14615	35211.000	4/02/19	446		100	35211.000	AU2
16793578	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	14615	35211.000	4/02/19	448		100	35211.000	AU2
16793578	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	14615	35211.000	4/02/19	449		100	35211.000	AU2
16793578	completed annual inspection only	14615	35211.000	5/01/19	9999999		100	35211.000	AUS
16793578	replaced coupler. had R.F.O tire replaced, did ann	14615	35211.000	5/01/19	9999999		100	35211.000	AUS
16776884	tightened all spool caps, cleaned mess, ck for lea	15109	35211.000	3/27/19	9999999		100	35211.000	AUS
16564051	OSR-LRO NAIL SHOULDER- PUT NEW SS TIRE ON.	99999	35211.000	1/11/19	9999999		100	35211.000	AUS

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

Cmpy: SS

Page: 22

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
16564051	OSR-DELIVERY FLEET REPAIR	99999	35211.000	1/11/19	9999999		100	35211.000	AUS
16324981	OSR-RR TIRE PATCHED.	99999	35211.000	10/15/18	9999999		100	35211.000	AUS
16324981	OSR-TIRE PTCHED	99999	35211.000	10/15/18	9999999		100	35211.000	AUS
16269018	REPLACE LRI/O TIRES W/NEW AND REPAIR RRO TIRE	TIR	35211.000	9/26/18	9999999		100	35211.000	AUS
16230872	nothing needed	17663	35211.000	9/13/18	9999999		100	35211.000	AUS
16230821	replace broken winch	17663	35211.000	9/13/18	9999999		100	35211.000	AUS
16230821	replaced winch cable	17663	35211.000	9/13/18	9999999		100	35211.000	AUS
16211737	INSTALL SENSORS IN RRI/O TIRES	TIR	35211.000	9/06/18	9999999		100	35211.000	AUS
16153055	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	15769	35211.000	8/16/18	20		100	35211.000	AU2
16153055	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	15769	35211.000	8/16/18	241		100	35211.000	AU2
16153055	SAFETY INSPECTION	15769	35211.000	8/16/18	242		100	35211.000	AU2
16153055	WARRANTY 1YR	15769	35211.000	8/16/18	255		210	35211.000	AU2
16153055	CHECK CONDITION OF PAINT AND DECALS	15769	35211.000	8/16/18	435		100	35211.000	AU2
16153055	GREASE AND ADJUST FIFTH WHEEL	15769	35211.000	8/16/18	446		100	35211.000	AU2
16153055	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	15769	35211.000	8/16/18	448		100	35211.000	AU2
16153055	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	15769	35211.000	8/16/18	449		100	35211.000	AU2
16153055	R&R BRAKES ON REAR AXLE. AMERICAN EQUIPMENT	15769	35211.000	8/16/18	9999999		100	35211.000	AU2
16153055	R&R BRAKE SHOES, DRUMS, AND HARDWARE ON REAR AXLE	15769	35211.000	8/21/18	9999999		100	35211.000	AU2
15991591	replaced remote, linked to receiver and test	15109	35211.000	6/28/18	9999999		100	35211.000	AUS
15910277	OSR-TIRE LUG AND UNLUG ON RF	99999	35211.000	5/24/18	9999999		100	35211.000	AUS
15910277	OSR-DELIVERY FLEET REPAIR	99999	35211.000	5/24/18	9999999		100	35211.000	AUS
15906603	OSR-TIRE PLUGGED PATCHED RR.	99999	35211.000	5/23/18	9999999		100	35211.000	AUS
15906603	OSR-DELIVERY FLEET REPAIR	99999	35211.000	5/23/18	9999999		100	35211.000	AUS
15881311	REPLACE TIRE SENSOR ON RFI TIRE	TIR	35211.000	5/15/18	9999999		100	35211.000	AUS
15880232	OSR-RE EPOXY THE SENSOR BACK IN TIRE.	99999	35211.000	5/14/18	9999999		100	35211.000	AUS
15880232	OSR-DELIVERY FLEET REPAIR	99999	35211.000	5/14/18	9999999		100	35211.000	AUS
15816565	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	17129	35211.000	4/23/18	241		100	35211.000	AUS
15816565	SAFETY INSPECTION	17129	35211.000	4/23/18	242		100	35211.000	AUS
15816565	WARRANTY 1YR	17129	35211.000	4/23/18	255		210	35211.000	AUS
15816565	REPACK WHEEL BEARINGS	17129	35211.000	4/23/18	315		100	35211.000	AUS
15816565	CHECK CONDITION OF PAINT AND DECALS	17129	35211.000	4/23/18	435		100	35211.000	AUS
15816565	GREASE AND ADJUST FIFTH WHEEL	17129	35211.000	4/23/18	446		100	35211.000	AUS
15816565	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	17129	35211.000	4/23/18	448		100	35211.000	AUS
15816565	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	17129	35211.000	4/23/18	449		100	35211.000	AUS
15816565	ANNUAL INSPECTION *(USE INSPECTION FORM)*	17129	35211.000	4/23/18	456		100	35211.000	AUS
15816565	COMPLETE PM SERVICE / AMERICAN EQUIPMENT	17129	35211.000	4/23/18	9999999		100	35211.000	AUS
15816565	FEDERAL ANNUAL INSP COMPLETE / AMERICAN EQUIPMENT	17129	35211.000	4/23/18	9999999		100	35211.000	AUS
15816565	COMPLETE SERVICE & INSPECTION / AMERICAN EQUIPMENT	17129	35211.000	5/04/18	9999999		100	35211.000	AUS
15745803	OSR-NEW SS TIRE PUT ON THE UNITS RF TIRE.	99999	35211.000	3/29/18	9999999		100	35211.000	AUS
15745803	OSR-MOUNT AND DISMOUNTED NEW SS TRIE	99999	35211.000	3/29/18	9999999		100	35211.000	AUS
15692278	TPMS INSTALL AND TIRE REPLACEMENT	TIR	35211.000	3/09/18	9999999		100	35211.000	AUS
15681736	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	13857	35211.000	3/07/18	20		100	35211.000	AUS
15681736	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13857	35211.000	3/07/18	241		100	35211.000	AUS
15681736	SAFETY INSPECTION	13857	35211.000	3/07/18	242		100	35211.000	AUS
15681736	WARRANTY 1YR	13857	35211.000	3/07/18	255		210	35211.000	AUS
15681736	CHECK CONDITION OF PAINT AND DECALS	13857	35211.000	3/07/18	435		100	35211.000	AUS
15681736	GREASE AND ADJUST FIFTH WHEEL	13857	35211.000	3/07/18	446		100	35211.000	AUS
15681736	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	13857	35211.000	3/07/18	448		100	35211.000	AUS
15681736	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	13857	35211.000	3/07/18	449		100	35211.000	AUS
15681736	BRAKE JOB FRONT AXLE. ADJUST & CHECK ALL BRAKES ON	13857	35211.000	3/07/18	9999999		100	35211.000	AUS
15681736	BOTH AXLES. WORK COMPLETED BY RUSH TRUCK.	13857	35211.000	3/07/18	9999999		100	35211.000	AUS
15681736	Rush replaced brakes	13857	35211.000	3/20/18	9999999		100	35211.000	AUS
15437540	OSR-LRI VALVE STEM REPLACED	99999	35211.000	12/06/17	9999999		100	35211.000	AUS

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cmpy: SS

Page: 23

- 99/99/99

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
15437540	OSR-LRI VALVE STEM REPLACED	99999	35211.000	12/06/17	9999999		100	35211.000	AUS
15418318	OSR-RRI TIRE PATCHED & REAPIRED	99999	35211.000	11/30/17	9999999		100	35211.000	AUS
15418318	OSR-RRI TIRE PATCHED & REPAIRED	99999	35211.000	11/30/17	9999999		100	35211.000	AUS
15377767	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	13193	35211.000	11/14/17	20		100	35211.000	AUS
15377767	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13193	35211.000	11/14/17	241		100	35211.000	AUS
15377767	WARRANTY 1YR	13193	35211.000	11/14/17	255		210	35211.000	AUS
15377767	REPACK WHEEL BEARINGS	13193	35211.000	11/14/17	315		100	35211.000	AUS
15377767	CHECK CONDITION OF PAINT AND DECALS	13193	35211.000	11/14/17	435		100	35211.000	AUS
15377767	changed rear hub oilers	13193	35211.000	11/14/17	9999999		100	35211.000	AUS
15377767	replaced rear oiler caps	13193	35211.000	11/14/17	9999999		100	35211.000	AUS
15375110	OSR-LR GATOR CAP R&R	99999	35211.000	11/14/17	9999999		100	35211.000	AUS
15375110	OSR-R&R LR GATOR CAP	99999	35211.000	11/14/17	9999999		100	35211.000	AUS
15343122	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	16386	35211.000	11/02/17	241		100	35211.000	AUS
15343122	SAFETY INSPECTION	16386	35211.000	11/02/17	242		100	35211.000	AUS
15343122	CHECK CONDITION OF PAINT AND DECALS	16386	35211.000	11/02/17	435		100	35211.000	AUS
15343122	GREASE AND ADJUST FIFTH WHEEL	16386	35211.000	11/02/17	446		100	35211.000	AUS
15343122	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	16386	35211.000	11/02/17	448		100	35211.000	AUS
15343122	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	16386	35211.000	11/02/17	449		100	35211.000	AUS
15343122	R&R 3 HYD CYLINDERS ON DOVETAIL/AMERICAN EQUIPMENT	16386	35211.000	11/02/17	9999999		100	35211.000	AUS
15319759	R&R dovetail cylinders. American Equipment	16386	35211.000	11/03/17	9999999		100	35211.000	AUS
15278585	OSR-PATCHED & REPAIRED RF TIRE	99999	35211.000	10/13/17	9999999		100	35211.000	AUS
15278585	OSR-PATCHED & REPAIRED RF TIRE	99999	35211.000	10/13/17	9999999		100	35211.000	AUS
15126068	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13193	35211.000	8/23/17	241		100	35211.000	AUS
15126068	SAFETY INSPECTION	13193	35211.000	8/23/17	242		100	35211.000	AUS
15126068	WARRANTY 1YR	13193	35211.000	8/23/17	255		210	35211.000	AUS
15126068	CHECK CONDITION OF PAINT AND DECALS	13193	35211.000	8/23/17	435		100	35211.000	AUS
15126068	GREASE AND ADJUST FIFTH WHEEL	13193	35211.000	8/23/17	446		100	35211.000	AUS
15126068	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	13193	35211.000	8/23/17	448		100	35211.000	AUS
15126068	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	13193	35211.000	8/23/17	449		100	35211.000	AUS
15126068	R&R KINGPIN. COMPLETED BY ASERO WELDING.	13193	35211.000	8/23/17	9999999		100	35211.000	AUS
15126068	R&R KING PIN. WORK COMPLETED BY ASERO WELDING	13193	35211.000	9/20/17	9999999		100	35211.000	AUS
15120322	OSR-LEFT REAR TIRE PATCHED AND REPAIRED	99999	35211.000	8/22/17	9999999		100	35211.000	AUS
15120322	OSR-LEFT REAR TIRE PATCHED AND REPAIRED	99999	35211.000	8/22/17	9999999		100	35211.000	AUS
15063231	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	15109	35211.000	8/03/17	20		100	35211.000	AUS
15063231	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	15109	35211.000	8/03/17	241		100	35211.000	AUS
15063231	SAFETY INSPECTION	15109	35211.000	8/03/17	242		100	35211.000	AUS
15063231	WARRANTY 1YR	15109	35211.000	8/03/17	255		210	35211.000	AUS
15063231	CHECK CONDITION OF PAINT AND DECALS	15109	35211.000	8/03/17	435		100	35211.000	AUS
15063231	GREASE AND ADJUST FIFTH WHEEL	15109	35211.000	8/03/17	446		100	35211.000	AUS
15063231	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	15109	35211.000	8/03/17	448		100	35211.000	AUS
15063231	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	15109	35211.000	8/03/17	449		100	35211.000	AUS
15063231	only replaced hub oiler and gsckt	15109	35211.000	8/03/17	9999999		100	35211.000	AUS
15063231	replaced oiler and gsckt. filled fluid level and ck	15109	35211.000	8/03/17	9999999		100	35211.000	AUS
15011865	OSR-RIGHT FRONT TIRE REPLACED	99999	35211.000	7/18/17	9999999		100	35211.000	AUS
15011865	OSR-RIGHT FRONT TIRE REPLACED	99999	35211.000	7/18/17	9999999		100	35211.000	AUS
14959287	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	15109	35211.000	6/28/17	241		100	35211.000	AUS
14959287	WARRANTY 1YR	15109	35211.000	6/28/17	255		210	35211.000	AUS
14959287	CHECK CONDITION OF PAINT AND DECALS	15109	35211.000	6/28/17	435		100	35211.000	AUS
14959287	only did srv repair, not ck srv	15109	35211.000	6/28/17	9999999		100	35211.000	AUS
14959287	reinstalled clevis and tightened all spool caps, t	15109	35211.000	6/28/17	9999999		100	35211.000	AUS
14957264	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	16386	35211.000	6/28/17	241		100	35211.000	AUS
14957264	SAFETY INSPECTION	16386	35211.000	6/28/17	242		100	35211.000	AUS
14957264	WARRANTY 1YR	16386	35211.000	6/28/17	255		210	35211.000	AUS

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

Cmpy: SS

Page: 24

- 99/99/99

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
14957264	CHECK CONDITION OF PAINT AND DECALS	16386	35211.000	6/28/17	435		100	35211.000	AUS
14957264	GREASE AND ADJUST FIFTH WHEEL	16386	35211.000	6/28/17	446		100	35211.000	AUS
14957264	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	16386	35211.000	6/28/17	448		100	35211.000	AUS
14957264	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	16386	35211.000	6/28/17	449		100	35211.000	AUS
14957264	R&R CYLINDER FOR DOVETAIL LOCK, HUB OILER GASKET, AND ADJUSTED 5TH WHEEL. ALL WORK COMPLETED BY	100000	35211.000	6/28/17	9999999		100	35211.000	AUS
14957264	AMERICAN EQUIPMENT	100000	35211.000	6/28/17	9999999		100	35211.000	AUS
14957264	R&R TAIL CYLINDER. R&R HUB GASKET. ADJUST 5TH WHEEL	16386	35211.000	7/12/17	9999999		100	35211.000	AUS
14940933	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13193	35211.000	6/22/17	241		100	35211.000	AUS
14940933	WARRANTY 1YR	13193	35211.000	6/22/17	255		210	35211.000	AUS
14940933	CHECK CONDITION OF PAINT AND DECALS	13193	35211.000	6/22/17	435		100	35211.000	AUS
14940933	R&R BRAKES REAR AXLE / AMERICAN EQUIPMENT	100000	35211.000	6/22/17	9999999		100	35211.000	AUS
14940933	Complete brake job. American Equipment to complete	13193	35211.000	6/26/17	9999999		100	35211.000	AUS
14900665	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	100000	35211.000	6/09/17	241		100	35211.000	AUS
14900665	SAFETY INSPECTION	100000	35211.000	6/09/17	242		100	35211.000	AUS
14900665	WARRANTY 1YR	13193	35211.000	6/09/17	255		210	35211.000	AUS
14900665	CHECK CONDITION OF PAINT AND DECALS	100000	35211.000	6/09/17	435		100	35211.000	AUS
14900665	GREASE AND ADJUST FIFTH WHEEL	100000	35211.000	6/09/17	446		100	35211.000	AUS
14900665	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	100000	35211.000	6/09/17	448		100	35211.000	AUS
14900665	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	100000	35211.000	6/09/17	449		100	35211.000	AUS
14900665	TRAILER PM SERVICE COMPLETED AMERICAN EQUIPMENT	100000	35211.000	6/09/17	9999999		100	35211.000	AUS
14900665	Trailer pm completed American Equipment	13193	35211.000	6/09/17	9999999		100	35211.000	AUS
14887500	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	16386	35211.000	6/06/17	241		100	35211.000	AUS
14887500	SAFETY INSPECTION	16386	35211.000	6/06/17	242		100	35211.000	AUS
14887500	WARRANTY 1YR	16386	35211.000	6/06/17	255		210	35211.000	AUS
14887500	CHECK CONDITION OF PAINT AND DECALS	16386	35211.000	6/06/17	435		100	35211.000	AUS
14887500	GREASE AND ADJUST FIFTH WHEEL	16386	35211.000	6/06/17	446		100	35211.000	AUS
14887500	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	16386	35211.000	6/06/17	448		100	35211.000	AUS
14887500	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	16386	35211.000	6/06/17	449		100	35211.000	AUS
14887500	ANNUAL INSPECTION *(USE INSPECTION FORM)*	16386	35211.000	6/06/17	456		100	35211.000	AUS
14887500	complete inspection	16386	35211.000	6/06/17	9999999		100	35211.000	AUS
14857652	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	15109	35211.000	5/25/17	241		100	35211.000	AUS
14857652	WARRANTY 1YR	15109	35211.000	5/25/17	255		210	35211.000	AUS
14857652	CHECK CONDITION OF PAINT AND DECALS	15109	35211.000	5/25/17	435		100	35211.000	AUS
14857652	rear axle brakes getting low	15109	35211.000	5/25/17	9999999		100	35211.000	AUS
14857652	replaced oiler, gskt and filled	15109	35211.000	5/25/17	9999999		100	35211.000	AUS
14797169	90 DAY BIT INSPECTION,(CALIFORNIA ONLY)	13193	35211.000	5/04/17	20		100	35211.000	AUS
14797169	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13193	35211.000	5/04/17	241		100	35211.000	AUS
14797169	SAFETY INSPECTION	13193	35211.000	5/04/17	242		100	35211.000	AUS
14797169	WARRANTY 1YR	13193	35211.000	5/04/17	255		210	35211.000	AUS
14797169	CHECK CONDITION OF PAINT AND DECALS	13193	35211.000	5/04/17	435		100	35211.000	AUS
14797169	GREASE AND ADJUST FIFTH WHEEL	13193	35211.000	5/04/17	446		100	35211.000	AUS
14797169	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	13193	35211.000	5/04/17	448		100	35211.000	AUS
14797169	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	13193	35211.000	5/04/17	449		100	35211.000	AUS
14797169	replaced right front hub cap	13193	35211.000	5/04/17	9999999		100	35211.000	AUS
14702390	OSR-LFO,LFI,RF,RFO TIRES REPLACED WORN OUT	99999	35211.000	4/03/17	9999999		100	35211.000	AUS
14702390	OSR-DELIVERY FLEET REPAIR	99999	35211.000	4/03/17	9999999		100	35211.000	AUS
14593872	pm completed by American equipment	13193	35211.000	2/27/17	9999999		150	35211.000	AUS
14580303	4-10R17.5 GL283A	TIR	35211.000	2/17/17	9999999		100	35211.000	AUS
14517379	OSR-TIRES REPLACED ON TRAILER LRLFRFRF ETC	99999	35211.000	1/26/17	9999999		100	35211.000	AUS
14517379	OSR-DELIVERY FLEET REPAIR	99999	35211.000	1/26/17	9999999		100	35211.000	AUS
14226342	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	100000	35210.000	10/07/16	241		100	35210.000	AUS
14226342	SAFETY INSPECTION	100000	35210.000	10/07/16	242		100	35210.000	AUS

12/15/22 14:03:03

System: SUNSTATE

Equipment: 144681

Equipment Maintenance History

Cmpy: SS

Page: 25

- 99/99/99

Cat/Class: 89-3000 TRAILERS

Status: Z From/To date:

<--- Filters

SMF#	Description	Mechanic	Meter out	Maint dt	Step #	Lbr hr	Lbcd	Meter in	Loc
14226342	CHECK CONDITION OF PAINT AND DECALS	100000	35210.000	10/07/16	435		100	35210.000	AUS
14226342	GREASE AND ADJUST FIFTH WHEEL	100000	35210.000	10/07/16	446		100	35210.000	AUS
14226342	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	100000	35210.000	10/07/16	448		100	35210.000	AUS
14226342	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	100000	35210.000	10/07/16	449		100	35210.000	AUS
14226342	PM SERVICE COMPLETED BY AMERICAN EQUIPMENT	100000	35210.000	10/07/16	9999999		100	35210.000	AUS
14223899	90 DAY BIT INSPECTION, (CALIFORNIA ONLY)	13193	35211.000	10/10/16	20		100	35211.000	AUS
14223899	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	13193	35211.000	10/10/16	241		100	35211.000	AUS
14223899	WARRANTY 1YR	13193	35211.000	10/10/16	255		210	35211.000	AUS
14223899	REPACK WHEEL BEARINGS	13193	35211.000	10/10/16	315		100	35211.000	AUS
14223899	CHECK CONDITION OF PAINT AND DECALS	13193	35211.000	10/10/16	435		100	35211.000	AUS
14223899	complete service	13193	35211.000	10/10/16	9999999		100	35211.000	AUS
14122346	OSR-RR INNER TIRE REPAIRED SCREW IN TIRE	99999	27104.000	9/06/16	9999999		100	27104.000	AUS
14122346	OSR-DELIVERY FLEET REPAIR	99999	27104.000	9/06/16	9999999		100	27104.000	AUS
14119963	OSR-REPLACED PATCH	99999	27104.000	9/02/16	9999999		100	27104.000	AUS
14119963	OSR-REPAIRED PATCH ON RR INNER TIRE	99999	27104.000	9/02/16	9999999		100	27104.000	AUS
14119963	OSR-REPLACED PATCH	99999	27104.000	9/02/16	9999999		100	27104.000	AUS
13951692	CHECK FOR HYD LEAK. REMOVE PANEL & INSTALL MISSING	100000	27104.000	6/29/16	9999999		100	27104.000	AUS
13951692	BOLT ON MANIFOLD BODY. CHECKED FOR AIR LEAKS. ALL	100000	27104.000	6/29/16	9999999		100	27104.000	AUS
13951692	WORK COMPLETED BY AMERICAN EQUIPMENT.	100000	27104.000	6/29/16	9999999		100	27104.000	AUS
13885231	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	800009	21301.000	6/03/16	241		100	21301.000	AUS
13885231	SAFETY INSPECTION	800009	21301.000	6/03/16	242		100	21301.000	AUS
13885231	CHECK CONDITION OF PAINT AND DECALS	800009	21301.000	6/03/16	435		100	21301.000	AUS
13885231	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	800009	21301.000	6/03/16	448		100	21301.000	AUS
13885231	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	800009	21301.000	6/03/16	449		100	21301.000	AUS
13885231	ANNUAL INSPECTION *(USE INSPECTION FORM)*	800009	21301.000	6/03/16	456		100	21301.000	AUS
13761727	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	100000	21301.000	4/25/16	241		100	21301.000	AUS
13761727	SAFETY INSPECTION	100000	21301.000	4/25/16	242		100	21301.000	AUS
13761727	CHECK CONDITION OF PAINT AND DECALS	100000	21301.000	4/25/16	435		100	21301.000	AUS
13761727	GREASE AND ADJUST FIFTH WHEEL	100000	21301.000	4/25/16	446		100	21301.000	AUS
13761727	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	100000	21301.000	4/25/16	448		100	21301.000	AUS
13761727	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	100000	21301.000	4/25/16	449		100	21301.000	AUS
13761727	PM SERVICE COMPLETED BY AMERICAN EQUIPMENT	100000	21301.000	4/25/16	9999999		100	21301.000	AUS
13546695	ROUTINE MAINTENANCE / REFER TO OPERATORS MANUAL	100000	10600.000	12/30/15	241		100		AUS
13546695	SAFETY INSPECTION	100000	10600.000	12/30/15	242		100		AUS
13546695	CHECK CONDITION OF PAINT AND DECALS	100000	10600.000	12/30/15	435		100		AUS
13546695	GREASE AND ADJUST FIFTH WHEEL	100000	10600.000	12/30/15	446		100		AUS
13546695	CHECK S CAM BUSHINGS AND GREASE AS NEEDED	100000	10600.000	12/30/15	448		100		AUS
13546695	CHECK SLACK ADJUSTERS AND GREASE AS NEEDED	100000	10600.000	12/30/15	449		100		AUS
13546695	FULL SERVICE PM COMPLETED BY AMERICAN EQUIPMENT	100000	10600.000	12/30/15	9999999		100		AUS

Total labor hours:

Total extended amount:

\$.00

*** End of report ***