



# Lubricant Analysis Report

North America: +1-877-808-3750  
 Latin America: +1-317-808-3750 / +502-3093-6466 (WhatsApp)  
 Europe: +1-317-808-3750

0	1	2	3	4
NORMAL		ABNORMAL	CRITICAL	

Overall report severity based on comments.

Account Information		Component Information		Sample Information	
Account Number: 153995-7777-0002 Company Name: BOOM AND BUCKET Contact: ADAM LAWRENCE/KRIS HUFF Address: C/O SAMIR SHAH ATHERTON, CA US Phone Number: 213-463-5980/775-225		Component ID: 2012 FREIGHTLINER Secondary ID: A5909592 Component Type: UNIDENTIFIED ENGINE Manufacturer: <a href="#">Information Requested</a> Model: <a href="#">Information Requested</a> Application: UNKNOWN Sump Capacity:		Tracking Number: 23265A85713 Lab Number: H-669545 Lab Location: Houston Data Analyst: ZXH Sampled: 27-Mar-2024 Received: 05-Apr-2024 Completed: 10-Apr-2024	
Filter Information		Miscellaneous Information		Product Information	
Filter Type: <a href="#">Information Requested</a> Micron Rating: 0				Product Manufacturer: <a href="#">Information Requested</a> Product Name: <a href="#">Information Requested</a> Viscosity Grade: <a href="#">Information Requested</a>	
Comments	Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. FUEL DILUTION is at a MODERATE LEVEL; In order to properly compare data to the correct standards, please provide COMPONENT MANUFACTURER and MODEL, and the FLUID MANUFACTURER, PRODUCT NAME, and VISCOSITY GRADE. Unit and/or lubricant TIME missing. The fuel dilution test was performed using the diesel method. Please specify if this sample is from a diesel or gasoline engine to ensure the appropriate fuel dilution method is utilized.				

Sample #	Wear Metals (ppm)										Contaminant Metals (ppm)			Multi-Source Metals (ppm)					Additive Metals (ppm)					
	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
1	10	0	0	2	2	0	0	0	1	0	4	1	2	0	8	1	0	0	6	51	2426	0	943	1077

Sample #	Sample Information								Contaminants			Fluid Properties					
	Date Sampled	Date Received	Lube Time	Unit Time	Lube Change	Lube Added	Filter Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100 °C	Acid Number	Base No. D4739	Oxidation	Nitration	
			h	h	Lube Change	gal	Filter Change	%	%	%	cSt	cSt	mg KOH / g	mg KOH / g	abs / cm	abs / 0.1mm	
1	27-Mar-2024	05-Apr-2024	0	0	Unk	0	Unk	3.8 - GC	<.1	<.1 - FTIR		11.4		6.07	8	6	

Sample #	Particle Count (particles/mL)									Test Method	Additional Testing	
	ISO Code	> 4	> 6	> 10	> 14	> 21	> 38	> 70	> 100			
	Based On	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL	particles / mL			
1	4/6/14	/ /										

Comments are advisory only and are based on the assumption that the sample and data submitted are valid. Results relate only to the items tested. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.