

1.0 Fahrassistenz-Paket. Ganzjahresreifen. Heckkla · 18 August
2026 · Eningen

Specifications

		Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRD36333
		Cylinder Capacity	1.000 ^{cm3}
Model	Focus SW		
Model Versions	1.0 Fahrassistenz-Paket. Ganzjahresreifen. Heckkla	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	01-08-2024
Body Type	5 door hatchback	Odometer	56.633 ^{Km}
Color	White	Numer Of Keys	1
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	85		

Images





Nachweise - Ablieferungs-Inspektion und Service

Ablieferungs-Inspektion	ATM
Datum: 03.05.2025	Strom & Co. AG
Kilometer: 25457	Grödenstr. 20
Inspektion durch: [Signature]	57189 Hückeswagen
Inspektion durch: [Signature]	Tel. 0420-110000



Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 03-09-2025

Last maintenance odometer 25.951

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	3 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Frontdoor – Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Wheelcover - Right Front

Damage Type

Broken

Repair Type

Replace

Acceptable

No



Damage Part

Bumper – Rear

Damage Type

Broken

Repair Type

Replace & Spray

Acceptable

No



Damage Part

Trunkshelf



Damage Type

Missing

Repair Type

Replace

Acceptable

No