


1.0 Ecoboost Hybrid · 18 August 2026

Specifications

		Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0NXXGCHNRD35086
		Cylinder Capacity	1.000 ^{cm3}
Model	Focus	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.0 Ecoboost Hybrid	First Admission	08-08-2024
Body Type	5 door hatchback	Odometer	62.198 ^{Km}
Color	Blue	Numer Of Keys	1
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	114		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel – Heated

Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 15-01-2026

Maintenance Remarks

Accu laden

Last maintenance odometer 46.080

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages

Acceptable



Damage Part

Damage Type

Repair Type

Acceptable

Interior

Stains & dirt

Cleaning

No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Left

Scratch(es)

Spotrepair

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right


Small scratch(es)

Acceptable

Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Small scratch(es)	Deurgreep	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Leftside	Previous Repair	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Small scratch(es)	Acceptable	Yes