

1.0 Ecoboost Hybrid · 18 August 2026 · Ehingen

Specifications

		Fuel Type	Gasoline
		VIN	WF0NXXGCHNRD33539
Manufacturer	FORD	Cylinder Capacity	1.000 ^{cm3}
Model	Focus	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.0 Ecoboost Hybrid	First Admission	08-08-2024
Body Type	5 door hatchback	Odometer	64.312 ^{Km}
Color	Silver	Numer Of Keys	1
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	114		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last maintenance odometer 61.636

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	3 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Interior

Stains & dirt

Cleaning

No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Left

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Scratch(es)

Spray

No



Damage Part
Alloy – Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No




Damage Part
spoiler FB

Damage Type
Scratch(es)

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Fender – Front Left

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Deurgreep	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Left	Dislocated / Loose	Slot	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Small scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small scratch(es)	Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Damaged	Middenconsole	Cloth Repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Dislocated / Loose	Instaplijst	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No