



Hyundai Santa Fe 2.2 CRDi Comfort

EZ 03/2012 | Geländewagen | Diesel | Schaltgetriebe | 127.126km
Besteuerung: Differenzbesteuert (§25a UStG)
Fahrzeugstandort: 96***
Fahrzeug aufgenommen am: 09.07.2026

Fahrzeugdaten

Hersteller Hyundai	Typ/Verkaufsbezeichnung Santa Fe 2.2 CRDi Comfort [DE - SUV5 2.2 CRDi DPF EU5, Comfort 4WD, (Facelift) 2010 - 2012]		
Kategorie Geländewagen	FIN KMHSH81XCBU784019	Kennzeichen -	Laufleistung laut Tacho 127.126km
HU bis / HU-Bericht vorhanden 05/2027 / Nicht Vorhanden	Polster Stoff	Leistung 197 PS (145 KW)	Kraftstoff Diesel
Anzahl Schlüssel 3	Serviceheft Ja	Scheckheftgepflegt Nein	
Hubraum 2.199 ccm	Bordmappe liegt vor	Letzter Service 80.353km	Letzter Service am 03/2020
Emissionsklasse Euro 5a	Sitze 5	Türen 4/5	Getriebe-Typ Schaltgetriebe
EZ 03/2012	Farbe Rot	Gesamtzahl der bekannten Halter 1	
Importfahrzeug Kein Reimportfahrzeug	CoC Dokumente vorhanden Ja	Land der letzten Zulassung Deutschland	
Untypische Vornutzung Keine		CO2-Emissionen 176g/km (NEFZ)	Kraftstoffverbrauch 6.8l/100km (NEFZ)

Hinweise zum Zustandsbericht

Besichtigungsbedingungen

Der vorliegende Zustandsbericht und die Bewertung der technischen Bauteile sowie der Fahrbereitschaft wurde ausschließlich basierend auf einer Sichtprüfung angefertigt. Eine ordnungsgemäße Sichtprüfung ist bei schwierigen Witterungsbedingungen bzw. Verschmutzung der Karosserie nur eingeschränkt möglich. In diesen Fällen können weitere Schäden nicht ausgeschlossen werden.

Bei der Besichtigung wurde keine Probefahrt durchgeführt und es kam keine Hebebühne zum Einsatz. Am Fahrzeug können der Laufleistung bzw. dem Alter entsprechende Mängel auftreten. Vorschäden waren CarOnSale, falls im Bericht nicht anders erwähnt, nicht bekannt.

Reifenzustand

1. Satz (Montiert)

Reifentyp: Allwetterreifen
Felge: Leichtmetall (Zoll: 17)

Vorne links	Vorne rechts	Hinten links	Hinten rechts
			
(2 mm)	(2 mm)	(5 mm)	(5 mm)
Kerben, Kratzer	Kerben, Kratzer	Kerben, Kratzer	Kerben, Kratzer

2. Satz

Reifentyp: vehicle.tire-type-label.without-tires
Felge: Leichtmetall (Zoll: 17)

Vorne links	Vorne rechts	Hinten links	Hinten rechts
			
-	-	-	-

Lackwerte

Fahrzeugteil	Lackschichtdicke (in µm)	Fahrzeugteil	Lackschichtdicke (in µm)
Fahrertür	130	Beifahrertür	125
Kotflügel vorne links	105	Kotflügel vorne rechts	155
Türe hinten links	120	Türe hinten rechts	115
Seitenteil hinten links	120	Seitenteil hinten rechts	115
Motorhaube	100	Heckklappe	115
Dach	115		



Technischer Zustand



Tonaufnahme des Motors:

[Hier die Tonaufnahme anhören](#)

Unterer Motorbereich	Keine Auffälligkeiten;
Schalt- / Automatikgetriebe	Keine Auffälligkeiten;
Lenkung	Keine Auffälligkeiten;
Batterie	Keine Auffälligkeiten;
Verteilergetriebe	Keine Auffälligkeiten;
Differential	Keine Auffälligkeiten;
Klimaanlage	Kühlleistung ungenügend;

Sonstige technische Mängel

Tür Hinten links lässt sich nicht öffnen

Zusatzinformationen

Eine Funkfernbedienung ohne Funktion;

Verschleißteile

Bremsanlage	Keine Auffälligkeiten;
Kupplung	Keine Auffälligkeiten;
Fahrwerk	Keine Auffälligkeiten;



Serienausstattung

- 3. Bremsleuchte
- Airbag Fahrer-/Beifahrerseite
- Anti-Blockier-System (ABS)
- Antriebsart: Allradantrieb permanent
- Audiosystem: Radio mit CD-Player (MP3-fähig)
- Außenspiegel lackiert
- Blinkleuchte in Außenspiegel integriert
- Bremsassistent
- Dachreling
- Elektr. Bremskraftverteilung
- Fensterheber elektrisch vorn + hinten
- Gepäcknetz im Koffer-/Laderaum
- Getriebe 6-Gang
- Airbag Beifahrerseite abschaltbar
- Alarmanlage mit Fernbedienung
- Antischlupfregelung (ASR)
- Audiobedienung am Lenkrad
- Außenspiegel elektr. verstell- und heizbar, beide
- Außentemperaturanzeige
- Bordcomputer
- Dachantenne
- Dachspoiler
- Elektron. Stabilitäts-Programm (ESP)
- Füllstandsanzeige Scheibenwaschanlage
- Gepäckraumabdeckung / Rollo
- Gurtstraffer

- | | |
|---|--|
| • Heckscheibe heizbar | • Heckscheibenwischer |
| • Isofix-Aufnahmen für Kindersitz | • Karosserie: 5-türig |
| • Kopf-Airbag-System | • Kühlergrill verchromt |
| • Lendenwirbelstütze Sitz vorn links, verstellbar | • Lenkrad (Leder) |
| • Lenksäule (Lenkrad) verstellbar | • Leuchtweitenregelung |
| • Mittelarmlehne hinten | • Mittelarmlehne hinten mit Getränkehalter |
| • Mittelarmlehne vorn mit Fach | • Modellpflege |
| • Motor 2,2 Ltr. - 145 kW CRDi KAT | • Nebelscheinwerfer |
| • Nebelschlussleuchte | • Original Fahrzeug Farbe: SUPERIOR RED |
| • Radiovorbereitung, 6 Lautsprecher | • Radstand 2700 mm |
| • Reserverad in Fahrbereifung | • Rußpartikelfilter |
| • Rücksitzlehne geteilt/klappbar | • Schadstoffarm nach Abgasnorm Euro 5 |
| • Schalt-/Wählhebelgriff Leder | • Scheibenwaschanlage |
| • Schmutzfänger hinten | • Schmutzfänger vorn |
| • Seitenairbag | • Seitenaufprallschutz |
| • Seitenschutzleisten | • Servolenkung |
| • Sitz vorn links höhenverstellbar | • Sitzbezug / Polsterung: Stoff |
| • Sonnenblenden mit Spiegel (beleuchtet) | • Stoßfänger lackiert |
| • Türgriffe außen Wagenfarbe | • USB-Anschluss + AUX-IN-Anschluss |
| • Verglasung getönt | • Wegfahrsperre |
| • Zentralverriegelung mit Fernbedienung | |



Sonderausstattung

Die Daten der Serien- und Sonderausstattung werden aus der DAT Datenbank übernommen. Es kann keine Haftung für die Vollständigkeit und Richtigkeit übernommen werden

Fahrzeugfotos












The image shows a document with several stamps and handwritten notes. At the top, there is a title 'Nichtschaden' and a subtitle 'Nichtschaden'. Below this, there are two main sections. The left section contains a stamp 'MRZ 17' and a stamp 'TUV NORD' dated 'April 23'. The right section contains a stamp 'TUV NORD' dated 'Mar 27' and a stamp 'TUV NORD' dated 'Mar 21'. There is also a circular seal from 'TUV NORD BREMEN'. Handwritten text includes 'MRZ 17', 'April 23', 'Mar 27', 'Mar 21', and 'Lok'. The document is titled 'Nichtschaden' and 'Nichtschaden'.

COMPLETE VEHICLES ECC CERTIFICATE OF CONFORMITY		VEHICLE CATEGORY M) (complete and completed vehicles)		Drinks	
Number of units		2 and above		30	
Type of vehicle		ECC Code		Type of study	
The assigned Position	S. B. Chu GENERAL MANAGER HONGKONG MOTOR VEHICLE	Number of units	2 and above	Drinks	30
Issued on/after that the vehicle		1. Forward view: position, position, dimensions	1. Forward view: position, position, dimensions	Drinks	30
1. Make (Trade name of manufacturer)	1. Make (Trade name of manufacturer)	2. Length	2. Length	Drinks	30
2. Type	2. Type	3. Width	3. Width	Drinks	30
3. Year	3. Year	4. Weight	4. Weight	Drinks	30
4. Model	4. Model	5. Max. speed	5. Max. speed	Drinks	30
5.2.2. General remarks	5.2.2. General remarks	6. Max. speed	6. Max. speed	Drinks	30
6. Vehicle Category	6. Vehicle Category	7. Max. speed	7. Max. speed	Drinks	30
7. Name and address of the manufacturer	7. Name and address of the manufacturer	8. Max. speed	8. Max. speed	Drinks	30
8. Name and address of the manufacturer	8. Name and address of the manufacturer	9. Max. speed	9. Max. speed	Drinks	30
9. Name and address of the manufacturer	9. Name and address of the manufacturer	10. Max. speed	10. Max. speed	Drinks	30
10. Name and address of the manufacturer	10. Name and address of the manufacturer	11. Max. speed	11. Max. speed	Drinks	30
11. Name and address of the manufacturer	11. Name and address of the manufacturer	12. Max. speed	12. Max. speed	Drinks	30
12. Name and address of the manufacturer	12. Name and address of the manufacturer	13. Max. speed	13. Max. speed	Drinks	30
13. Name and address of the manufacturer	13. Name and address of the manufacturer	14. Max. speed	14. Max. speed	Drinks	30
14. Name and address of the manufacturer	14. Name and address of the manufacturer	15. Max. speed	15. Max. speed	Drinks	30
15. Name and address of the manufacturer	15. Name and address of the manufacturer	16. Max. speed	16. Max. speed	Drinks	30
16. Name and address of the manufacturer	16. Name and address of the manufacturer	17. Max. speed	17. Max. speed	Drinks	30
17. Name and address of the manufacturer	17. Name and address of the manufacturer	18. Max. speed	18. Max. speed	Drinks	30
18. Name and address of the manufacturer	18. Name and address of the manufacturer	19. Max. speed	19. Max. speed	Drinks	30
19. Name and address of the manufacturer	19. Name and address of the manufacturer	20. Max. speed	20. Max. speed	Drinks	30
20. Name and address of the manufacturer	20. Name and address of the manufacturer	21. Max. speed	21. Max. speed	Drinks	30
21. Name and address of the manufacturer	21. Name and address of the manufacturer	22. Max. speed	22. Max. speed	Drinks	30
22. Name and address of the manufacturer	22. Name and address of the manufacturer	23. Max. speed	23. Max. speed	Drinks	30
23. Name and address of the manufacturer	23. Name and address of the manufacturer	24. Max. speed	24. Max. speed	Drinks	30
24. Name and address of the manufacturer	24. Name and address of the manufacturer	25. Max. speed	25. Max. speed	Drinks	30
25. Name and address of the manufacturer	25. Name and address of the manufacturer	26. Max. speed	26. Max. speed	Drinks	30
26. Name and address of the manufacturer	26. Name and address of the manufacturer	27. Max. speed	27. Max. speed	Drinks	30
27. Name and address of the manufacturer	27. Name and address of the manufacturer	28. Max. speed	28. Max. speed	Drinks	30
28. Name and address of the manufacturer	28. Name and address of the manufacturer	29. Max. speed	29. Max. speed	Drinks	30
29. Name and address of the manufacturer	29. Name and address of the manufacturer	30. Max. speed	30. Max. speed	Drinks	30
30. Name and address of the manufacturer	30. Name and address of the manufacturer	31. Max. speed	31. Max. speed	Drinks	30
31. Name and address of the manufacturer	31. Name and address of the manufacturer	32. Max. speed	32. Max. speed	Drinks	30
32. Name and address of the manufacturer	32. Name and address of the manufacturer	33. Max. speed	33. Max. speed	Drinks	30
33. Name and address of the manufacturer	33. Name and address of the manufacturer	34. Max. speed	34. Max. speed	Drinks	30
34. Name and address of the manufacturer	34. Name and address of the manufacturer	35. Max. speed	35. Max. speed	Drinks	30
35. Name and address of the manufacturer	35. Name and address of the manufacturer	36. Max. speed	36. Max. speed	Drinks	30
36. Name and address of the manufacturer	36. Name and address of the manufacturer	37. Max. speed	37. Max. speed	Drinks	30
37. Name and address of the manufacturer	37. Name and address of the manufacturer	38. Max. speed	38. Max. speed	Drinks	30
38. Name and address of the manufacturer	38. Name and address of the manufacturer	39. Max. speed	39. Max. speed	Drinks	30
39. Name and address of the manufacturer	39. Name and address of the manufacturer	40. Max. speed	40. Max. speed	Drinks	30
40. Name and address of the manufacturer	40. Name and address of the manufacturer	41. Max. speed	41. Max. speed	Drinks	30
41. Name and address of the manufacturer	41. Name and address of the manufacturer	42. Max. speed	42. Max. speed	Drinks	30
42. Name and address of the manufacturer	42. Name and address of the manufacturer	43. Max. speed	43. Max. speed	Drinks	30
43. Name and address of the manufacturer	43. Name and address of the manufacturer	44. Max. speed	44. Max. speed	Drinks	30
44. Name and address of the manufacturer	44. Name and address of the manufacturer	45. Max. speed	45. Max. speed	Drinks	30
45. Name and address of the manufacturer	45. Name and address of the manufacturer	46. Max. speed	46. Max. speed	Drinks	30
46. Name and address of the manufacturer	46. Name and address of the manufacturer	47. Max. speed	47. Max. speed	Drinks	30
47. Name and address of the manufacturer	47. Name and address of the manufacturer	48. Max. speed	48. Max. speed	Drinks	30
48. Name and address of the manufacturer	48. Name and address of the manufacturer	49. Max. speed	49. Max. speed	Drinks	30
49. Name and address of the manufacturer	49. Name and address of the manufacturer	50. Max. speed	50. Max. speed	Drinks	30
50. Name and address of the manufacturer	50. Name and address of the manufacturer	51. Max. speed	51. Max. speed	Drinks	





Fahrzeug Schadenfotos (Außen)



Stoßstange vorne (Kratzer)




Stoßstange vorne (Kratzer)



Stoßstange vorne (Kratzer)



Motorhaube (Delle)



Motorhaube (Delle)



Rad (Kerben, Kratzer)



Rad (Kerben, Kratzer)



Rad (Kerben, Kratzer)



Rad (Kerben, Kratzer)



Fahrtür (Kratzer, Rost)



Fahrtür (Kratzer, Rost)



Fahrtür (Kratzer)



Beifahrertür (Kratzer)




Beifahrertür (Kratzer)



Beifahrertür (Kratzer)



Türe hinten links (Kratzer)



Türe hinten links (Kratzer)



Türe hinten rechts (Kratzer)



Türe hinten rechts (Kratzer)



Stoßstange hinten (Kratzer)



Stoßstange hinten (Kratzer)



Stoßstange hinten (Kratzer)



Stoßstange hinten (Kratzer)



Stoßstange hinten (Kratzer)



Schweller links (Kratzer)



Kotflügel vorne links (Kratzer)



Kotflügel vorne links (Kratzer)



Kotflügel vorne rechts (Kratzer)




Kotflügel vorne rechts (Kratzer)



Seitenteil hinten links (Kratzer)



Seitenteil hinten links (Kratzer)



Seitenteil hinten rechts (Kratzer)



Seitenteil hinten rechts (Kratzer)



Heckklappe (Kratzer)



Heckklappe (Kratzer)



Heckklappe (Rost)

Fahrzeug Schadenfotos (Innen)



Innenraum (Verschleiß)



Innenraum (Verschleiß)