

# FITNESS CERTIFICATE OF SCHOOL BUILDING

(To be filled by Inspecting Officer)

- 1 Name of School : **ST.Elizabeth Public UP School**  
**Kariappally,Vellora**
- 2 Name of Officer : Seethal V, Assistant engineer, LSGD (EW), Eramam Kuttur section.
- 3 Location : Kariappally Thaliparamba North
- 4 Period of which the certificate is issued : 2023-2024
- 5 Type of building : Permanent

## RCC Roof

6.80x6.60x3.70 m	3 Nos GF
6.90x6.80x3.70 m	1 No GF
6.60x6.90x3.70 m	2 Nos GF
6.80x6.60x3.70 m	3 Nos FF
6.90x6.60x3.70 m	1 No FF
6.90x6.80x3.70 m	1 No FF
6.60x6.90x3.70 m	2 Nos FF
27.90x6.60x3.70 m	1 No SF
6.60x6.90x3.70 m	2 Nos SF
6.90x6.80x3.70 m	1 No SF

- 6 Nature of defect if any :
- a) Foundation and basement : Nil.
- b) Super structure : Nil.
- c) Doors and structure : Nil.
- d) Wood work wrought and put up : Nil.
- e) Roof : Nil.
- f) Flooring : Nil.
- g) Miscellaneous : Nil.
- 7 Any major defects notice which will render the building unsafe in any manner : Nil.
- 8 Whether maintenance works have been done properly : Yes..
- 9 Whether the structure is sound for conducting class : Yes - Upto 31.05.2024 (Under normal weather and wind condition).

Note: 1 The stability of the structure should be examined also with reference to the altitude, intensity of wind, exposure to flood etc.

2 Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on 29-05-2023, and found to be fit to conduct classes for the period for the reasons stated above.

*Isabel*  
**Dr. Isabel Thottakkara**  
**PRINCIPAL**  
**ST. ELIZABETH PUBLIC SCHOOL**  
**KARIAPPALLY, VELLORA P O**

*S*  
**MANAGER**  
**ST. ELIZABETH PUBLIC SCHOOL**  
**KARIAPPALLY, VELLORA (P.O.)**  
**KANNUR-670 306**



Signature :

Designation:

*Seethal V*  
Assistant Engineer,

Local Self Government Department,

Page 11 of 22 Eramam Kuttur Section.

SEETHAL V  
PEN: 498091  
ASSISTANT ENGINEER &  
SUPERSTRUCTURE WING  
ERAMAM KUTTUR SECTION