

ePIPE® Stops Plumbing Problems in Their Tracks for The Towers at Forest Acres in Columbia, South Carolina

THE PROBLEM

When the copper water pipes in The Towers at Forest Acres — a 186-unit apartment complex — began to fail, the building owners faced a big problem: pinhole leaks were popping up everywhere. The plumbing system was made up of ½" to 2 ½" supply lines and hidden inside concrete walls and floors across two large buildings.

These leaks weren't just a major inconvenience for residents; they were steadily compromising the property's infrastructure. The choice was clear: either rip out and replace the entire system with a costly, disruptive traditional approach or find a smarter, faster solution that would protect the property and keep residents happy.



THE SOLUTION

That's where we came in. With our patented ePIPE® no-mess, in-place pipe restoration process, there's no need to tear apart walls or floors. Our team restored the complex's aging copper pipes right where they were, creating a durable, long-lasting protective barrier from the inside out. The best part? We completed the entire project on schedule with minimal disruption to residents' daily lives. No headaches, no downtime—just a stronger, leak-free plumbing system that the owners and tenants could count on for years to come.

If you're a property decision-maker facing similar issues, make sure to **contact us today for a consultation.**