

Vehicle Report

FIRST.CHECK

Full History / Valuation Report – Incl Claim History

VOLKSWAGEN

Polo Vivo 1.4 63kW Comfortline 5-dr [2022-2024]

Model Year / Warranty Start: 2022



PROVIDED DATA

VIN # AAVZZZ6RZPU004432

REPORT DATA

VIN # AAVZZZ6RZPU004432

Engine CLP405058

Colour DARK BLUE METALLIC

New/Retail Price R 263,000.00

*Indicative image only — actual model and colour may differ.

Vehicle Values

RETAIL ESTIMATED VALUE

Retail Estimate R 216,300.00

Retail Estimate Low R 192,200.00

Retail Estimate High R 240,400.00

TRADE-IN ESTIMATED VALUE

Trade-in Estimate R 179,600.00

Trade-in Estimate Low R 159,600.00

Trade-in Estimate High R 199,600.00

Stolen Police Interest



Active Police Interest **Provided VIN not reported as wanted**

The information regarding police interest in this report is based on the VIN and/or License plate provided by the user, as well as the Engine Number obtained through an automated search.

It is important to confirm that the identifiers used match those associated with the vehicle.

Vehicle Finance



Active finance on VIN provided. Current title holder: **ABSA**

Microdot Verification



Microdot Fitted **No**

RECENT MARKET SALES of similar vehicles

2026-02-19 CITY OF JOHANNESBURG R 199,999.00

2026-01-31 NKOMAZI R 229,988.00

2025-12-23 MATJHABENG R 200,000.00

Accident & Claim History



✓ No processed insurance claims found

Important Note: This search reflects available insurance database records. It does not cover unreported damage or cash repairs.

Recommendation: Database checks are not a substitute for a physical check. FirstCheck highly recommends booking a physical inspection at an approved centre (e.g. DEKRA) before purchase.

FirstCheck accepts no liability for loss or damage resulting from reliance on this report.

ENDORSED BY /



Detailed vehicle specifications

VEHICLE DETAILS

Manufacturer	VOLKSWAGEN
Type	VW Polo Vivo
Model	Polo Vivo 1.4 63kW Comfortline 5-dr [2022-2024]
Introduction Date	2022-10
Discontinue Date	2024-08
Market	Passenger
Vehicle Code	Pvkpv23002
Power (kw)	63
Body Shape	Hatch (5-dr)
Drive Type	4x2
Fuel Type	Petrol

VEHICLE DETAILS cont

Engine Size (cc)	1398
Transmission Type	Manual

VERIFICATION DETAILS

Colour	DARK BLUE METALLIC
Engine Number	CLP405058
Vehicle Code	Pvkpv23002
VIN	AAVZZZ6RZPU004432
Warranty Start	2022

SERVICE AND MAINTENANCE

Warranty's - km's	120 000
Warranty's - Years	3
Service Plan - km's	Optional
Service Plan - Years	Optional
Maintenance Plan - km's	Optional
Maintenance Plan - Years	Optional
Service Intervals - km's	15 000

FIRSTCHECK REPORT ID: 9B8VPL0S

DATE: 07-03-2026

FIRST.CHECK

Disclaimer: The vehicle information displayed by FirstCheck is sourced from multiple data providers and is presented solely for informational purposes. While we endeavour to ensure the accuracy and completeness of this information, it may not reflect the vehicle's full history and could contain errors or omissions. Please note that the year model indicated is based on the warranty start, and the vehicle may have been registered in the following year. We strongly advise verifying the year model on the RCI Enatis vehicle licence document. By using this service, you acknowledge and accept that FirstCheck (Pty) Ltd shall not be held liable for any loss or damage arising from reliance on or use of this information.

ENDORSED BY /





Report Number: TOPDON1772521003

SN: 110499X5E204RJ

Date Created: 2026-03-03

TOPDON ID: L9DJXN6X79

VOLKSWAGEN-6RS - Polo Vivo 2018 >-2023_Pre-Scan_Full System Report

Plate Number:MB38WBGP

Make:VOLKSWAGEN

Model:6RS - Polo Vivo 2018 >

Year:2023

Distance Traveled:35206 miles

Engine:CLP405058

Sub Model:

Diagnostic Time:2026-03-03 08:56:43

Vehicle Software Version:V5.60

Diagnostic Application Version:V6.20.004

VIN:AAVZZZ6RZPU004432

Diagnostic Scan Path:6RS - Polo Vivo 2018 >\2023

Customer:

Phone Number of Customer:0837440206

Ticket No.:

Summary

10 systems were scanned, and 5 of them were detected with DTCs. Altogether 7 DTCs were found. For safe driving, please read the report carefully and perform related repair in a timely manner.

Full System Report (10)

Pre-Scan

System

System Status

01 - Engine Control Module 1

Fault

2

03 - Brakes 1

Fault

2

04 - Steering Angle Sender

No fault

0

09 - Central Electrics	No fault	0
15 - Airbag	Fault	1
17 - Dash Board	No fault	0
19 - Gateway	Fault	1
25 - Immobilizer	No fault	0
44 - Steering Assistance	Fault	1
56 - Radio	No fault	0

01 - Engine Control Module 1

DTC	Description	Status
P0300:00/00768:00 0	Fuel Volume Regulator 'A' Control Circuit Low	Active/Static
P0302:00/00770:00 0	Cyl.2 Misfire Detected	Active/Static

03 - Brakes 1

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	passive/sporadic
C102D00	Tire pressure warning	active/static

15 - Airbag

DTC	Description	Status
-----	-------------	--------

19 - Gateway

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

44 - Steering Assistance

DTC	Description	Status
U111100	Function restriction due to missing message	passive/sporadic

Image



Disclaimer

This diagnostic report is provided for the purpose of displaying diagnostic data and is for reference only. It does not constitute any judgment, conclusion, or basis for action. The Company shall not be liable for any decisions or actions taken by the user based on the content of this report.

When a user chooses to save the diagnostic report to the App client, the relevant report content will be stored in accordance with the App's functional requirements for the purpose of subsequent access.