



Floor Plan // Room Dimensions




FLOOR 1



FLOOR 2

*\*Disclaimer*

3DR.Tours has taken utmost care in the accuracy of these measurements to RECA standards based upon the reliability of the equipment used and expertise of their personnel. However, 3DR.Tours cannot be responsible to provide an exact measurement and final measurements may vary to +/- 1 percent. Further, 3DR.Tours disclaims any liability for loss, damage, or manipulation relating to the information and data provided and it's use from here on.



## Notes // Documentation

<b>Name:</b>	Vincent Chuippi
<b>Property Address:</b>	15741 108 ave
<b>Date Measured (mm/dd/yy):</b>	11/27/18
<b>Measurement Equipment:</b>	Lasers and tape measure

	Metric (m <sup>2</sup> )	Imperial (ft <sup>2</sup> )
<b>Total RMS:</b>	89.2	960
<b>Floor 1 (Basement)</b>	78.2	842
<b>Floor 2 (Main Level)</b>	89.2	960
<b>Floor 3</b>		0
<b>Floor 4</b>		0
<b>Floor 5</b>		0
<b>Other</b>		0

### How Measurements Were Achieved:

Measurements were acquired using lasers for the interior area which were then extrapolated to include the thickness of the exterior walls recorded with a tape measure according to RMS regulations for extrapolating exterior measurements.

### Notes:

No additional info