
INSTALLATION INSTRUCTIONS

Copy Part# 170023, Rev. C, 12/2013

Page 1 of 1

CAPILANO SEAL KIT # HS5171 **CAPILANO 1350 HELMS**



ITEM	PART #	QTY	DESCRIPTION
1	210428	1	Shaft Seal, Gaco
2	010322	2	O-Ring .210, 70 Dur N
3	015824	2	O-Ring .011, 70 Dur N
4	045124	2	O-Ring .017, 70 Dur N
5	046127	2	Gasket

ITEM	PART #	QTY	DESCRIPTION	



INSTALLATION INSTRUCTIONS

Copy Part# 310631, Rev. B, 01/2014

Page 1 of 1

SYSTEM WARNING DECAL INSTALLATION

This kit contains a warning decal (see Figure A) that is to be installed immediately adjacent to the helm pump. This warning decal is to be installed to instruct users on all points to be checked prior to each use. Checking these simple points prior to use may bring attention to possible faults within the system or steering gear which must be corrected prior to use.

♠ WARNING

Failure to install this decal may lead to loss of steering control. leading to possible ejection from vessel causing property damage. personal injury and/or death.

A WARNING

Fallure to adhere may result in joss of steering control, leading to possible ejection from vessel causing property damage, personal injury and/or death. Consult Owner's Manuel for more information. Prior to EVERY use:

- Verify immediate steering response when lurning steering wheel(s).
- Inspect all steering hoses and littings for waar, kinking or leaks,

Check fluid level in highest • Check for binding, loose, beim pump. • worn or leaking steering components.

DO NOT operate boat if any component is not in proper working candition. Maintain steering system minimum twice per year. 828057

Figure A. Decal PID# 828067.

If you have any questions or if you require additional decals, please contact SeaStar Solutions Technical Support by:

Email: seastar@seastarsolutions.com

Phone: 604-248-3858

Web: www.seastarsolutions.com