

NEW PRODUCT!

Announcement Number: S04091901

#JF015E-PISTON

JATCO/NISSAN JF015E/RE0F11A

CNC machined billet steel
replacement upper primary piston





Don't overlook this very common hidden failure. This piston **MUST BE PRESS-FIT** or it will leak.

Slipping pulleys, with or without codes, get worse when hot. This is likely due to upper primary pulley ID piston damage. The upper primary piston's inner seal is press-fit onto the shoulder of the pulley sheave. A worn or loose fitting piston leaks primary pulley-pressure, causing the belt to slip.



Primary pulley assembly



Secondary pulley assembly

ENGINEERED FOR PERFORMANCE.

DESIGNED FOR DURABILITY.

©TransGo. All rights reserved. TransGo®, Shift Kit®, SK® and Reprogramming Kit™ are registered and licensed trademarks.









